

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Oct 2024)

Parts: M1-MPV TOYOTA SIENTA 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Yew Tee Automobile Tech Pte Ltd/SMF5384Z/04/10/2024 14:39

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER <i>Dehnd</i>	0.00	0.00	*480.00 F <i>✓160</i>
2	1		*REAR BUMPER SIDE RETAINER LH <i>Dehd</i>	0.00	0.00	*80.00 F <i>✓50</i>
3	1		*REAR BUMPER SIDE RETAINER RH <i>Dehd</i>	0.00	0.00	*80.00 F <i>✓50</i>
4	1		*REAR BUMPER BRACKET LH <i>3 new</i>	0.00	0.00	*65.00 F <i>+</i>
5	1		*REAR BUMPER BRACKET RH <i>3 new Dehd</i>	0.00	0.00	*65.00 F <i>✓40</i>
6	1		*REAR BUMPER TOP GARNISH (BLACK) <i>Dehd</i>	0.00	0.00	*130.00 F <i>✓70</i>
7	1		*REAR BUMPER SIDE TOP GARNISH LH (BLACK) <i>new</i>	0.00	0.00	*170.00 F <i>+</i>
8	1		*REAR BUMPER SIDE TOP GARNISH RH (BLACK) <i>Dehd</i>	0.00	0.00	*170.00 F <i>✓40</i>
9	1		*REAR BUMPER SIDE TOP GARNISH LH (BLACK) REFLECTOR <i>new</i>	0.00	0.00	*90.00 F <i>+</i>
10	1		*REAR BUMPER SIDE TOP GARNISH RH (BLACK) REFLECTOR <i>crushed</i>	0.00	0.00	*90.00 F <i>✓35</i>
11	1		*REAR TAILGATE <i>Distorted</i>	0.00	0.00	*780.00 F <i>✓480</i>
12	1		*REAR TAILGATE RUBBER <i>Forw</i>	0.00	0.00	*230.00 F <i>✓150</i>
13	1		*REAR TAILGATE LOCK <i>Dehd new</i>	0.00	0.00	*320.00 F <i>+</i>
14	1		*REAR TAILGATE LOCK CATCH <i>new</i>	0.00	0.00	*56.00 F <i>+</i>
15	1		*REAR TAILGATE INNER BOARD <i>Dehd</i>	0.00	0.00	*130.00 F <i>✓40</i>
16	1		*REAR TAILGATE INNER BOARD HANDLE <i>new</i>	0.00	0.00	*56.00 F <i>+</i>
17	1		*REAR TAILGATE HINGES LH <i>3 Bent</i>	0.00	0.00	*75.00 F <i>✓45</i>
18	1		*REAR TAILGATE HINGES RH	0.00	0.00	*75.00 F <i>✓45</i>
19	1		*REAR TAILGATE DAMPER LH <i>3 new</i>	0.00	0.00	*160.00 F <i>+</i>
20	1		*REAR TAILGATE DAMPER RH <i>3 new</i>	0.00	0.00	*160.00 F <i>+</i>
21	1		*REAR TAILGATE LOGO <i>3 Not</i>	0.00	0.00	*48.00 F <i>✓4x</i>
22	1		*REAR TAILGATE SIENTA EMBLEM <i>3 New</i>	0.00	0.00	*48.00 F <i>✓4x</i>
23	1		*REAR TAILGATE HYBRID EMBLEM	0.00	0.00	*64.00 F <i>✓4x</i>
24	1		*REAR TAILGATE REFLECTOR LH <i>new</i>	0.00	0.00	*440.00 F <i>+</i>
25	1		*REAR TAILGATE REFLECTOR RH <i>crushed</i>	0.00	0.00	*440.00 F <i>✓160</i>
26	1		*REAR TAILGATE OUTER CHROME <i>new</i>	0.00	0.00	*320.00 F <i>+</i>
27	1		*REAR NUMBER PLATE LAMP LH <i>3 Not</i>	0.00	0.00	*70.00 F <i>+</i>
28	1		*REAR NUMBER PLATE LAMP RH <i>3 Not</i>	0.00	0.00	*70.00 F <i>+</i>
29	1		*REAR WINDSCREEN GLASS <i>Shattered</i>	0.00	0.00	*480.00 F <i>✓300</i>
30	1		*REAR TAILLAMP LH <i>new</i>	0.00	0.00	*350.00 F <i>+</i>
31	1		*REAR TAILLAMP RH <i>Missing</i>	0.00	0.00	*350.00 F <i>✓170</i>
32	1		*REAR TAILLAMP PANEL RH <i>Repair</i>	0.00	0.00	*210.00 F <i>✓80</i>
33	1		*REAR TAILLAMP LOWER BRACKET RH <i>crushed</i>	0.00	0.00	*60.00 F <i>✓55</i>
34	1		*REAR FENDER TOP RH <i>Crushed new</i>	0.00	0.00	*480.00 F <i>✓48</i>
35	1		*REAR FENDER LOWER RH <i>Repair</i>	0.00	0.00	*560.00 F <i>+</i>
36	1		*REAR END PANEL <i>Bent</i>	0.00	0.00	*290.00 F <i>✓200</i>
37	1		*REAR END PANEL INNER GARNISH <i>Crushed</i>	0.00	0.00	*140.00 F <i>✓90</i>

F=Franchise part.

Sub Total (\$\$) 7,882.00

+ Margin on L,N Items 10.00% (\$\$) 788.20

Yew Tee Automobile Tech Pte Ltd/SMF5384Z/04/10/2024 14:39. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

10/7/24, 2:19 PM

Repairer Estimates

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
Total Parts (S\$)						8,670.20

Yew Tee Automobile Tech Pte Ltd/SMF5384Z/04/10/2024 14:39. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	REAR BUMPER SENSOR (SET) <i>standard.</i>	200.00 <i>+ 200</i>
2	1	REAR NUMBER PLATE <i>the n</i>	35.00 <i>+</i>
3	1	REAR WINDSCREEN SEALANT <i>new</i>	24.00 <i>✓</i>
Sub Total (\$\$)			259.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO ELECTRICAL WIRING SERVICES	New	30.00 <i>✓</i>
2	TO DISMANTLE & REFIT REAR SENSORS	New	60.00 <i>50</i>
3	TO DISMANTLE & REFIT REAR WINDSCREEN GLASS	New	100.00 <i>✓</i>
4	TO REMOVE, REFIX, REALIGN, ADJUST AND REPLACE ALL DAMAGED PARTS	New	2,800.00 <i>800</i>
5	TO UNDERCOATING FOR RUST PROTECTION	New	60.00 <i>40</i>
6	TO SPRAY PAINTING ACCIDENT PORTION	New	1,500.00 <i>800</i>
Gross Labour Cost (\$\$)			4,550.00

Yew Tee Automobile Tech Pte Ltd/SMF5384Z/04/10/2024 14:39. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L'ly
P/P 07/08/24
Not Authorised
Excess: To be advised
06 Days.