

ASSIGNMENT

From: _____ Date: _____

Estim: _____

OD / TP RES / TP RES / OD RES / EVA / INV / MV

To In _____ Vehicle No: _____

at _____

of _____

Insured: _____

Policy No: _____

Claim No: _____

Sum Insured: _____ Excess: _____

(Client Record)

Make of Vehicle: _____

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMFS3842 Yr Regn: 2018 / Nov

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Sienta C.C. 1496

Colour: Brown A/C: Insured / Std / NI / NA

Sp. Reading: 53505 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MHFZ28H3300059966

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/50R16

R: 195/50R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

GT.

Front

Rear

R/Bal. 06 mm

R/Bal. 06 mm

L/Bal. 06 mm

L/Bal. 06 mm

D.O.A.

D.O.I. 07/10/24

Survey held at Yew Tee

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

00 ECICS

COE Expiry :

Estimate given during : Yes ✓

1st Survey : No C

MV : 60K

PV : 262K

Nett : 39.8K

Date/Time, File Pass to?

☐ : Prel. Report

1) Date/Time, File Return to?

☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

3 + RS. \$1

Photos

Others

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invoice (\$

Report Format:

Report Format: F.P.R. / C.R.

Yew Tee Automobile Tech Pte Ltd

39 Woodlands Close #01-12, Mega@Woodlands

Singapore 737856

Tel: 62562081 Email: info@yewteegroup.com

INSURER:

ECICS Limited (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MPC23A00335301	Date of Loss:	21/09/2024
Vehicle Reg. No.:	SMF5384Z	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SYED FESHAL BIN S ABDULRAB TALIB		
Driver:	SYED FESHAL BIN S ABDULRAB TALIB		
Make/Model:	TOYOTA SIENTA, 1.5 (A)	Vehicle Reg. Date:	16/11/2018
Vehicle Colour:	BROWN		
Engine No:	2NRX397895	Chassis No:	MHFZ28H3300059966
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	15		
Present Location:	YEW TEE AUTOMOBILE TECH PTE LTD (WOODLANDS)		

COST OF CLAIMS

	Amount
Parts	8,670.20
Miscellaneous Items	259.00
Labour	4,550.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	13,479.20
+ GST 9.00% (S\$)	1,213.13
Nett Amount (S\$)	14,692.33

This claim is handled by: TOH TZE CHANG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 04 Oct 2024)
Parts: M1-MPV	TOYOTA SIENTA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: Yew Tee Automobile Tech Pte Ltd/SMF5384Z/04/10/2024 14:39	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER <i>Dehnd</i>	0.00	0.00	*480.00 F ✓
2	1		*REAR BUMPER SIDE RETAINER LH <i>He m</i>	0.00	0.00	*80.00 F ✓
3	1		*REAR BUMPER SIDE RETAINER RH ?	0.00	0.00	*80.00 F ?
4	1		*REAR BUMPER BRACKET LH <i>3 new</i>	0.00	0.00	*65.00 F +
5	1		*REAR BUMPER BRACKET RH <i>new</i>	0.00	0.00	*65.00 F +
6	1		*REAR BUMPER TOP GARNISH (BLACK) <i>Dehnd</i>	0.00	0.00	*130.00 F +
7	1		*REAR BUMPER SIDE TOP GARNISH LH (BLACK) <i>new</i>	0.00	0.00	*170.00 F +
8	1		*REAR BUMPER SIDE TOP GARNISH RH (BLACK) <i>Dehnd</i>	0.00	0.00	*170.00 F +
9	1		*REAR BUMPER SIDE TOP GARNISH LH (BLACK) REFLECTOR <i>new</i>	0.00	0.00	*90.00 F +
10	1		*REAR BUMPER SIDE TOP GARNISH RH (BLACK) REFLECTOR <i>cracked</i>	0.00	0.00	*90.00 F +
11	1		*REAR TAILGATE <i>Distorted</i>	0.00	0.00	*780.00 F ?
12	1		*REAR TAILGATE RUBBER ?	0.00	0.00	*230.00 F ?
13	1		*REAR TAILGATE LOCK ?	0.00	0.00	*320.00 F +
14	1		*REAR TAILGATE LOCK CATCH <i>new</i>	0.00	0.00	*56.00 F +
15	1		*REAR TAILGATE INNER BOARD ?	0.00	0.00	*130.00 F +
16	1		*REAR TAILGATE INNER BOARD HANDLE	0.00	0.00	*56.00 F +
17	1		*REAR TAILGATE HINGES LH <i>Not new</i>	0.00	0.00	*75.00 F +
18	1		*REAR TAILGATE HINGES RH	0.00	0.00	*75.00 F +
19	1		*REAR TAILGATE DAMPER LH	0.00	0.00	*160.00 F +
20	1		*REAR TAILGATE DAMPER RH	0.00	0.00	*160.00 F +
21	1		*REAR TAILGATE LOGO <i>new</i>	0.00	0.00	*48.00 F ✓
22	1		*REAR TAILGATE SIENTA EMBLEM	0.00	0.00	*48.00 F ✓
23	1		*REAR TAILGATE HYBRID EMBLEM <i>new</i>	0.00	0.00	*64.00 F ✓
24	1		*REAR TAILGATE REFLECTOR LH <i>new</i>	0.00	0.00	*440.00 F +
25	1		*REAR TAILGATE REFLECTOR RH <i>cracked</i>	0.00	0.00	*440.00 F +
26	1		*REAR TAILGATE OUTER CHROME <i>new</i>	0.00	0.00	*320.00 F +
27	1		*REAR NUMBER PLATE LAMP LH <i>Not new</i>	0.00	0.00	*70.00 F +
28	1		*REAR NUMBER PLATE LAMP RH <i>Not new</i>	0.00	0.00	*70.00 F +
29	1		*REAR WINDSCREEN GLASS <i>Shattered</i>	0.00	0.00	*480.00 F ✓
30	1		*REAR TAILLAMP LH <i>new</i>	0.00	0.00	*350.00 F +
31	1		*REAR TAILLAMP RH <i>Missing</i>	0.00	0.00	*350.00 F +
32	1		*REAR TAILLAMP PANEL RH <i>Repair</i>	0.00	0.00	*210.00 F +
33	1		*REAR TAILLAMP LOWER BRACKET RH ?	0.00	0.00	*60.00 F ✓
34	1		*REAR FENDER TOP RH <i>Cracked?</i>	0.00	0.00	*480.00 F +
35	1		*REAR FENDER LOWER RH <i>Repair</i>	0.00	0.00	*560.00 F +
36	1		*REAR END PANEL ?	0.00	0.00	*290.00 F ?
37	1		*REAR END PANEL INNER GARNISH ?	0.00	0.00	*140.00 F ?

F=Franchise part.

Sub Total (\$\$)

7,882.00

+ Margin on L,N Items 10.00% (\$\$)

788.20

Yew Tee Automobile Tech Pte Ltd/SMF5384Z/04/10/2024 14:39. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
Total Parts (S\$)						8,670.20

Yew Tee Automobile Tech Pte Ltd/SMF5384Z/04/10/2024 14:39. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	REAR BUMPER SENSOR (SET) <i>MT</i>	200.00 <i>+</i>
2	1	REAR NUMBER PLATE <i>MT</i>	35.00 <i>+</i>
3	1	REAR WINDSCREEN SEALANT <i>MT</i>	24.00 <i>✓</i>
Sub Total (S\$)			259.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO ELECTRICAL WIRING SERVICES	New	30.00 <i>✓</i>
2	TO DISMANTLE & REFIT REAR SENSORS	New	60.00 <i>50</i>
3	TO DISMANTLE & REFIT REAR WINDSCREEN GLASS	New	100.00 <i>✓</i>
4	TO REMOVE, REFIX, REALIGN, ADJUST AND REPLACE ALL DAMAGED PARTS	New	2,800.00 <i>800</i>
5	TO UNDERCOATING FOR RUST PROTECTION	New	60.00 <i>40</i>
6	TO SPRAY PAINTING ACCIDENT PORTION	New	1,500.00 <i>800</i>
Gross Labour Cost (S\$)			4,550.00

Yew Tee Automobile Tech Pte Ltd/SMF5384Z/04/10/2024 14:39. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Admin Lhy
PIP 07/08/24
Not Authorised
Excess: To be advised
06 Days.