



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMQ 6315J

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SUNDRIES (SN)	NECESSARY	\$150.00	\$150.00
1	FRT BUMPER LH INSERT (SN)	SERVICEABLE	\$15.85	\$0.00
1	FRT BUMPER RH INSERT (SN)	SERVICEABLE	\$15.85	\$0.00
1	FRT LH SIDE PANEL TOP MOUNTING (SN)	SERVICEABLE	\$57.55	\$0.00
1	FRT RH SIDE PANEL TOP MOUNTING (SN)	SERVICEABLE	\$57.55	\$0.00
1	LH FOG LAMP SUPPORT (SN)	CRACKED	\$165.15	\$165.15
1	LH MOUNTING PMA SENSOR (SN)	SERVICEABLE	\$23.65	\$0.00
1	FRT BUMPER TOP CARRIER (SN)	BENT	\$420.15	\$420.15
1	LH FINISHER (SN)	CRACKED	\$55.45	\$55.45
1	LH MOLDING (SPORT) (SN)	CRACKED	\$62.55	\$62.55
1	IMPACT ABSORBER TOP (SN)	CRACKED	\$64.00	\$64.00
1	TRIM STRIP CENTRE (SPORT) (SN)	CUT	\$55.05	\$55.05
1	COVERING CENTER (SN)	SERVICEABLE	\$76.40	\$0.00
1	FRT BUMPER PANEL PRIMED (BASIS) (SN)	DEFORMED	\$987.80	\$987.80
1	LH GRID LATERAL (LINES/PDC) (SN)	CRACKED	\$102.35	\$102.35
1	FRT LH GRILLE (SN)	CRACKED	\$125.55	\$125.55
2	GROMMET (SN)	NOT NECESSARY	\$1.60	\$0.00
1	LH BOTTOM ADAPTER (SN)	SERVICEABLE	\$112.30	\$0.00
1	LH AIR DUST DISPLACED RADIATOR (SN)	CRACKED	\$81.35	\$81.35
1	AIR DUCT (SN)	CRACKED	\$562.10	\$562.10
1	PLAQUE 82MM (SN)	NECESSARY	\$76.55	\$76.55
1	LH HEADLIGHT LED TECHNOLOGY (SN)	BROKEN	\$2,503.55	\$2,503.55
1	ULTRASONIC SENSOR BLACK (SN)	SERVICEABLE	\$269.65	\$0.00
6	DECOUPING RING PDC TORQUE CONVERTER (SN)	NOT NECESSARY	\$33.90	\$0.00
1	ULTRASONIC SENSOR SIDE (SN)	SERVICEABLE	\$391.40	\$0.00
1	EXTERNAL RADIATOR (SN) (ADDITIONAL)	BENT	\$564.95	\$564.95
1	BONNET (SN) (ADDITIONAL)	BENT	\$1,396.80	\$1,396.80
1	LH VERTICAL STRUT (SN) (ADDITIONAL)	BENT	\$55.65	\$55.65
1	GRATE CENTRE CLOSED (LINES/PDC) (SN) (ADDITIONAL)	CRACKED	\$170.55	\$170.55



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	LH SUPPORT HEADLIGHT ARM (SN) (ADDITIONAL)	BENT	\$134.50	\$134.50
1	LABEL COOLANT 520+/- 15G (SN) (ADDITIONAL)	NECESSARY	\$26.85	\$26.85
			\$8,816.60	\$7,760.90

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REPLACE FRONT BUMPER PANEL, BONNET, FRONT AIR DUCT, LH AIR DUCT DISPLACED RADIATOR, LH SUPPORT HEADLIGHT ARM, FRONT LH GRILLE, LH GRID LATERAL, TRIM STRIP CENTRE, TOP IMPACT ABSORBER, LH MOULDING, LH FINISHER, FRONT TOP CARRIER, GRATE CENTRE CLOSED, LH FOG LAMP SUPPORT, LH VERTICAL STRUCT INCLUDE CARRYING OUT OTHER NECESSARY REPAIRS CAUSED BY THE ACCIDENT		\$3,400.00	\$2,550.00
	TO SPRAY PAINT FRONT BUMPER AND BONNET		\$2,336.00	\$2,336.00
	TO CHECK ELECTRICAL WIRING SYSTEM AT THE FRONT SECTION FOR PROPER FUNCTION		\$177.00	\$177.00
	TO REPLACE LEFT HEADLIGHT		\$481.00	\$481.00
	TO CARRY BODY CAVITY PRESERVATION (X1) (PER PANEL) (ADDITIONAL)		\$118.00	\$118.00
	TO REMOVE PDC ASSEMBLY, REPLACE DAMAGED PARTS INCLUDE RECONNECTING TO BUMPER AND CONDUCTING CHECKS FOR PROPER FUNCTION (ADDITIONAL)		\$177.00	\$177.00
	TO REPLACE EXTERNAL RADIATOR ASSEMBLY INCLUDE PRESSURE TESTS, BLEED COOLING SYSTEM AND CONDUCTING CHECKS FOR LEAK (ADDITIONAL)		\$767.00	\$767.00
			\$7,456.00	\$6,606.00

GRAND TOTAL	\$16,272.60	\$14,366.90
--------------------	--------------------	--------------------

RECOMMENDED COST OF REPAIRS		\$14,366.90
LESS EXCESS		(\$500.00)
NETT LIABILITY		\$13,866.90

Report Ref No: CS/UOI24100126/Rqh3e2

MRB

MOHAMMED RASUL BIN MOHD YUNUS

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.