

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/ICS24100129/KQH3E2**Date:** 02/01/2025REFERENCE

Handling Insurer: ECICS Limited Policy No:

**Claimant Vehicle No :** GBE5995X **Insured Vehicle No :** GBH2224S

Date of Loss: 04/10/2024 Nature of Claim: TP Claim No: DMCV2400212H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBE5995X**

Make & Model: NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD EURO 5 (M) Engine No: ZD30007664N

Reg. Date: 23/01/2016 (Man. Year: 2015) Chassis No: JN1SC2F24Z0858065

Colour: White Odometer: 129864 km

Engine Capacity: 2953 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15X8 Rear Tyre Size: 155 R12X8 (D)

Front Left Side: West Lake 4 mm Rear Left Side: Falken 8/8 mm

Front Right Side: West Lake 4 mm Rear Right Side: Falken 8/8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	14,050.00	6,890.60	7,159.40	50.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,150.00	1,600.00	2,550.00	61.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>18,200.00</b>	<b>8,490.60</b>	<b>9,709.40</b>	<b>53.35</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>6,250.00</b>		
<b>(\$\$)</b>	18,200.00	6,250.00	11,950.00	65.66
<b>+ GST 9.00/9.00% (\$\$)</b>	1,638.00	562.50	1,075.50	65.66
<b>Nett Amount (\$\$)</b>	<b>19,838.00</b>	<b>6,812.50</b>	<b>13,025.50</b>	<b>65.66</b>

INSPECTION

Date of Assignment: 07/10/2024

Date Inspected: 02/12/2024 Inspected At: Abwin Service Pte Ltd (575721)  
176 Sin Ming Drive, #01-11 Autocare  
Singapore 575721

Estimated Period of Repair: 8.0 days

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 02 Jan 2025)	
<b>Parts:</b>	N/A	NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBE5995X)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT GRILLE	Cracked	725.00 F	*578.60 FL
2	1		*FRONT GRILLE EMBLEM	Necessary	79.00 F	*79.00 FL
3	1		*CABSTAR LOGO	Not Necessary	55.00 F	*- FL
4	1		*BUMPER FRONT	Bent	1,303.00 F	*945.00 FL
5	1		*HEADLAMP LH	Cracked	615.00 F	*615.00 FL
6	1		*CORNER PANEL LH	Serviceable	472.50 F	*- FL
7	1		*SIDE MIRROR LH	Serviceable	222.00 F	*- FL
8	1		*SIDE MIRROR HOLDER LH	Repair	269.00 F	*- FL
9	1		*SPARE TYRE PANEL	Repair	1,800.00 F	*- FL
10	1		*NUMBER PLATE FRONT	Bent	50.00 FS	*25.00 FS
11	1		*NUMBER PLATE REAR	Bent	50.00 FS	*25.00 FS
12	1		*REAR CABIN DOOR LH	Bent	1,550.00 FS	*1,550.00 FS
13	1		*REAR CABIN DOOR RH	Bent	1,550.00 FS	*1,550.00 FS
14	1		*REAR CABIN DOOR HINGE RH	Repair	280.00 FS	*- FS
15	1		*REAR CABIN DOOR HINGE LH	Distorted	280.00 FS	*280.00 FS
16	1		*SIGNAL LAMP LH	Broken	219.90 F	*219.90 FL
17	1		*SIGNAL LAMP LH COVER	Broken	89.60 F	*89.60 FL
18	1		*HEADLAMP BRACKET LH	Mtg Cracked	59.60 F	*59.60 FL
19	1		*END PANEL	Bent	1,233.90 F	*597.30 FL
20	1		*VERTICAL PANEL	Repair	1,022.90 F	*- FL
21	1		*VERTICAL SUPPORT PANEL	Repair	1,378.60 F	*- FL
22	1		*REAR CABIN SPONGE LH	Not Necessary	120.00 FS	*- FS
23	1		*70KM STICKER	Necessary	45.00 FS	*15.00 FS
24	1		*REAR CABIN LOCK RH	Bent	580.00 FS	*580.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>14,050.00</b>	<b>7,209.00</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	0.00	318.40
<b>Total Parts (\$\$)</b>	<b>14,050.00</b>	<b>6,890.60</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS	New	1,800.00	1,000.00
2	TO SPRAY PAINT ON AFFECTED AREAS	New	1,800.00	400.00
3	TO APPLY UNDERCOATING FOR RUST PROOFING	New	200.00	0.00
4	TO REALIGN FRONT CABIN	New	350.00	200.00
<b>Gross Labour Cost (S\$)</b>			<b>4,150.00</b>	<b>1,600.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >