

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24100133/UMA3Q2
Date: 19/11/2024

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D23MPC0006815
Claimant Vehicle No : SND1255M Insured Vehicle No : SLG5493Z
Date of Loss: 04/10/2024 Nature of Claim: TP Claim No: MPC2024D0011712

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SND1255M
Make & Model: HONDA ACCORD, 2.0 VTIS 5AT (A) Engine No: R20Z21600033
Reg. Date: 01/08/2016 (Man. Year: 2016) Chassis No: MRHCR1630GP000003
Colour: Grey Odometer: 147819 km
Engine Capacity: 1997 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/50 R17 Rear Tyre Size: 215/50 R17
Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,383.92	4,051.36	1,332.56	24.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,990.00	1,590.00	1,400.00	46.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,373.92	5,641.36	2,732.56	32.63
Approved Total (Overridden) (S\$)		4,500.00		
Nett Amount (S\$)	8,373.92	4,500.00	3,873.92	46.26
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		4,902.18		

INSPECTION

Date of Assignment: 07/10/2024
Date Inspected: 07/10/2024 Inspected At: Hup Motor Trading & Service (HQ)
Blk 9004 Tampines Street 93, #01-120
Singapore 528838
Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA Manager: Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Nov 2024)
Parts:	143	HONDA ACCORD 2.0 VTIS 5AT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SND1255M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*O/S HEAD LAMP ASSY	Cracked	2,949.90 FL	*2,880.90 FL
2	1		*O/S HEAD LAMP LOWER BRACKET	Cracked	46.20 FL	*46.20 FL
3	1		*FRONT BUMPER	Cut / Torn	650.50 FL	*620.50 FL
4	1		*FRONT BUMPER O/S SIDE RETAINER	Cracked	38.40 FL	*38.40 FL
5	10		*FRONT BUMPER CLIPS	Necessary	49.00 FL	*49.00 FL
6	1		*FRONT BUMPER O/S SIDE BRACKET	Not Necessary	5.90 FL	*- FL
7	1		*FRONT O/S FENDER	Buckled	597.60 FL	*597.60 FL
8	1		*FRONT O/S FENDER INNER SHIELD GUARD	Torn	239.30 FL	*239.30 FL
9	8		*FRONT O/S FENDER INNER SHIELD CLIPS	Necessary	31.20 FL	*31.20 FL
10	1		*FRONT BUMPER O/S FOG LAMP GARNISH	Not Necessary	165.10 FL	*- FL
11	1		*FRONT GRILLE	Not Necessary	564.50 FL	*- FL
12	1		*FRONT GRILLE TOP CHROME MOULDING	Cracked	470.30 FL	*470.30 FL
13	8		*FRONT GRILLE CLIPS	Not Necessary	39.20 FL	*- FL
14	1		*WASHER TANK	Deformed	90.80 FL	*90.80 FL
15	1		*FRONT SUPPORT PANEL	Repair	792.00 FL	*- FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (S\$)	6,729.90 5,064.20
					- List Item Discount on L Items 20.00/20.00% (S\$)	1,345.98 1,012.84
					Total Parts (S\$)	5,383.92 4,051.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO WIRING CHECK UP & ADJUST HEADLIGHT ALIGNMENT	New	50.00	20.00
2	TO CHECK & ADJUST FRONT WHEEL ALIGNMENT & BALANCING	New	150.00	60.00
3	TO RESPRAY TUFF-KOTE ON ALL AFFECTED ACCIDENT PARTS	New	90.00	30.00
4	LABOUR CHARGES TO REMOVE & CUT OUT DAMAGED PARTS ,TO JACK STRAIGHTEN & KNOCKING OUT FRONT SUPPORT PANEL,FRONT BONNET,FRONT SUPPORT PANEL & NECESSARY PARTS ,TO WELD ,RENEW & ALIGN ABOVE PARTS	New	1,250.00	680.00
5	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS	New	1,450.00	800.00
Gross Labour Cost (\$\$)			2,990.00	1,590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >