

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24100135/UUA3Q2

Date: 05/05/2025

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D24MCV0007498
Claimant Vehicle No :	FBU1268D	Insured Vehicle No :	PD8288Z
Date of Loss:	20/09/2024	Nature of Claim:	TP
		Claim No:	MCV2024D0011875

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBU1268D	Engine No:	HIDDEN
Make & Model:	RAP IONA AKA OAK, (A)	Chassis No:	SA1HDSGC0NC000056
Reg. Date:	19/08/2022 (Man. Year: 2022)	Odometer:	4851 km
Colour:	Green/Blue		
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110-90-12	Rear Tyre Size:	130-60-13
Front Left Side:	Presa 7 mm	Rear Left Side:	CST 7/7 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	911.00	319.50	591.50	64.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	448.00	200.00	248.00	55.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,359.00	519.50	839.50	61.77
+ GST 9.00/9.00% (S\$)	122.31	46.76	75.55	61.77
Nett Amount (S\$)	1,481.31	566.26	915.05	61.77
+ Loss of Use (2.0 x S\$20.00/day) (S\$)		40.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		608.44		

INSPECTION

Date of Assignment:	07/10/2024	
Date Inspected:	07/10/2024 Inspected At:	Ban Hock Hin Co. Pte Ltd (HQ) BLK 8 Defu South Street 1, #04-28 JTC Defu Industrial City Singapore 533758
Estimated Period of Repair:	2.0 days	

Adjuster: MARCUS CHUA

Manager: NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 24 Mar 2025)	
Parts:	N/A	RAP IONA AKA OAK (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBU1268D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*MUDGUARD FRONT	Broken	99.00 F	*99.00 FL
2	1		*RIM FRONT ASSY	Repair	392.00 F	*- FL
3	1		*SENSOR WHEEL SPEED	Torn	124.00 F	*124.00 FL
4	1		*SIGNAL FRONT LH ASSY	Cracked	132.00 F	*132.00 FL
5	1		*SET STEERING CONE	Not Necessary	164.00 F	*- FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (\$\$)	911.00 355.00
					- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00 35.50
					Total Parts (\$\$)	911.00 319.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TRANSPORT CHARGES (MOTORCYCLE) OVERSIZED	New	108.00	0.00
2	LABOUR QUOTED FOR DISMANTLE AND INSTALLATION OF PARTS	New	340.00	200.00
Gross Labour Cost (S\$)			448.00	200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >