



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJU 7039P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	BROKEN	700.00	700.00
10	FRONT BUMPER CLIP @\$5.00	NECESSARY	50.00	30.00
1	FRONT BUMPER RETAINER RH	NOT NECESSARY	50.00	-
1	FRONT BUMPER RETAINER LH	NOT NECESSARY	50.00	-
1	FRONT REINFORCEMENT	NOT NECESSARY	480.00	-
1	FRONT SPONGE/ ABSORBER	NOT NECESSARY	200.00	-
1	FRONT LICENSE GARNISH	NOT NECESSARY	60.00	-
1	FRONT HEADLAMP RH	NOT NECESSARY	600.00	-
1	FRONT HEADLAMP LH	CUT	600.00	600.00
1	FRONT SUPPORT PANEL	NOT NECESSARY	500.00	-
1	FRONT BONNET	DENTED	800.00	800.00
10	FRONT BONNET INSULATOR CLIP @\$5.00	NECESSARY	50.00	20.00
1	FRONT BONNET LOCK	NOT NECESSARY	80.00	-
1	FRONT BONNET / TOP COVER RUBBER SEAL	CRUSHED	50.00	50.00
1	FRONT BONNET HINGE RH	NOT NECESSARY	50.00	-
1	FRONT BONNET HINGE LH	NOT NECESSARY	50.00	-
1	AC CONDENSER	NOT NECESSARY	800.00	-
1	RADIATOR	NOT NECESSARY	650.00	-
	LESS 10% DISCOUNT		-	-220.00
			5,820.00	1,980.00
<u>SPECIAL NETT ITEMS</u>				
1	FRONT GRILLE ASSY (SN)	BROKEN	580.00	300.00
1	FRONT NUMBER PLATE WITH FRAME (SN)	NOT NECESSARY	40.00	-
1	COOLANT FLUID 4 LITRES (SN)	NOT NECESSARY	35.00	-
			655.00	300.00
<u>LABOUR</u>				
	SPRAY PAINTING FRONT BUMPER, FRONT BONNET, FRONT SUPPORT PANEL INCLUDING BLENDING.		700.00	400.00
	REMOVE AND REFIT FRONT & REAR AFFECTED AREA.		700.00	400.00
	REMOVE AND REFIT A/C CONDENSER, RADIATOR INCLUDING A/C GAS.	NOT NECESSARY	100.00	-

Report Ref No. CS/SPF24100136/Evh3m4(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	APPLY RUST PROOFING ON REPLACED/REPAIRED PANEL.		100.00	20.00
	CHECK AND RECTIFY ELECTRICAL WIRING.		30.00	30.00
			1,630.00	850.00
GRAND TOTAL			8,105.00	3,130.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,500.00

Report Ref No. CS/SPF24100136/Evh3m4(N)

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500-\$3,000

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.