

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24100138/ANH3E2
Date: 07/11/2024REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	SLK6433U	Insured Vehicle No :	SKZ8183K
Date of Loss:	04/10/2024	Nature of Claim:	TP
		Claim No:	DMPC2401340H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK6433U	Engine No:	161101W0173204DTD
Make & Model:	JAGUAR XE 2.0 I4D TSS, 2.0 D (A)	Chassis No:	SAJAB4AN8HA974848
Reg. Date:	23/01/2017 (Man. Year: 2016)	Odometer:	102839 km
Colour:	Blue		
Engine Capacity:	1999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %	
Parts	16,858.09	7,691.03	9,167.06	54.38	
Miscellaneous Items	0.00	0.00	0.00		
Labour	3,220.00	1,450.00	1,770.00	54.97	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
Calculated Gross Total (S\$)	20,078.09	9,141.03	10,937.06	54.47	
Approved Total (Overridden) (S\$)		7,300.00			
	(S\$)	20,078.09	7,300.00	12,778.09	63.64
+ GST 9.00/9.00% (S\$)		1,807.03	657.00	1,150.03	63.64
Nett Amount (S\$)	21,885.12	7,957.00	13,928.12	63.64	

INSPECTION

Date of Assignment:	07/10/2024	
Date Inspected:	07/10/2024 Inspected At:	Auto Bolt Services Pte Ltd (HQ) 8 KAKI BUKIT AVENUE 4, PREMIER @ KAKI BUKIT #03-55 Singapore 415875
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source:	(Last Synchronised: 05 Nov 2024)
Parts:	N/A JAGUAR XE 2.0 I4D TSS 2.0 D (A) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK6433U)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,672.50 FL	*1,672.50 FL
2	1		*REAR BUMPER LOWER PANEL	Deformed	875.20 FL	*530.00 FL
3	1		*BUMPER BRACKET CENTRE	Cracked	114.90 FL	*114.90 FL
4	1		*RIGHT HAND BUMPER BRACKET	Not Necessary	153.20 FL	*- FL
5	1		*LEFT HAND BUMPER BRACKET	Not Necessary	153.20 FL	*- FL
6	1		*PARKING AID SENSOR REAR (4PCS)	Damaged (2Pcs Only)	1,362.00 FL	*681.00 FL
7	1		*REAR PANEL	Repair	3,219.10 FL	*- FL
8	1		*BUMPER BEAM REAR	Dented	865.30 FL	*865.30 FL
9	1		*REAR BOOT	Dented	2,577.90 FL	*2,577.90 FL
10	1		*REAR LATCH	Damaged	322.90 FL	*322.90 FL
11	1		*REAR LATCH ACTUATOR	Not Necessary	223.40 FL	*- FL
12	1		*REAR LATCH COVER	Not Necessary	84.40 FL	*- FL
13	1		*REAR LATCH STRICKER	Not Necessary	84.40 FL	*- FL
14	1		*REAR BOOT SEAL	Not Necessary	325.30 FL	*- FL
15	1		*REAR STRUT	Not Necessary	1,417.40 FL	*- FL
16	1		*REAR STRUT SPRING	Not Necessary	206.30 FL	*- FL
17	1		*REAR GAS STRUT	Not Necessary	148.90 FL	*- FL
18	1		*RIGHT HAND WHEELARCH REAR	Not Necessary	437.80 FL	*- FL
19	1		*LEFT HAND WHEELARCH REAR	Not Necessary	437.80 FL	*- FL
20	1		*INNER TAIL LAMP RH	Cracked	676.10 FL	*676.10 FL
21	1		*INNER TAIL LAMP LH	Cracked	676.10 FL	*676.10 FL
22	1		*EXHAUST PIPE SILENCER (LOCAL REPAIR)	Bent	2,276.80 FN	*300.00 F
23	1		*SILENCER MOUNTING	Not Necessary	180.70 FL	*- FL
24	1		*INSULATOR REAR	Not Necessary	88.50 FL	*- FL
25	1		*TOWING COVER REAR	Deformed	40.00 FL	*40.00 FL
26	10		*BUMPER CLIP	Necessary	100.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (S\$)	18,720.10	8,506.70
- List Item Discount on L Items 10.00/10.00% (S\$)	1,634.33	815.67
- Nett Item Discount on N Items 10.00/0.00% (S\$)	227.68	0.00
Total Parts (S\$)	16,858.09	7,691.03

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING WITH REPLACE ALL THE PARTS	New	1,800.00	600.00
2	SPRAY PAINT	New	800.00	600.00
3	TO RESPRAY TUFF COAT TO AFFECTED AREA	New	200.00	30.00
4	CHECK WIRING, REAR TAIL LAMP & PARK AID	New	300.00	100.00
5	USE COMPUTER TO CLEAR FAULT CODE	New	120.00	120.00
			Gross Labour Cost (\$)	3,220.00
				1,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >