



RW AUTOMOTIVE APPRAISERS SERVICES
(Licensed Appraisers Claims Adjusters)
256 Bishan St. 22 #12-472 Singapore 570256
Tel +65 6996 9988 Hp: +65 8338 9988
Email: rw9988@yahoo.com Reg. 52821270B

INVOICE

HC Auto Pte. Ltd. Invoice No : **240016**
160 Sin Ming Drive
#05-09, Sin Ming Auto City Date : **13.06.2024**
Singapore 575722
On behalf of Samwoh Premix Pte. Ltd.

Being:		
Survey Fees (including 46 photographs and transport charges)		\$ 736.00
S'pore Dollars : Seven Hundred and Thirty-Six only.		<u>\$ 736.00</u>
Our Reference No. : RW/0016/24TP		
Vehicle No. : XE 2917 G		

SURVEYED WITHOUT PREJUDICE

RICHARD WONG
(Licensed Appraiser)



RW AUTOMOTIVE APPRAISERS SERVICES
(Licensed Appraisers Claims Adjusters)
256 Bishan St. 22 #12-472 Singapore 570256
Tel +65 6996 9988 Hp: +65 8338 9988
Email: rw9988@yahoo.com Reg. 52821270B

Samwoh Premix Pte. Ltd.
c/o HC Auto Pte. Ltd.
160 Sin Ming Drive
#05-09, Sin Ming Auto City
Singapore 575722

Report No : RW/0016/24TP
Date : 13.06.2024

VEHICLE INSPECTION REPORT

REFERENCE

Requested by : Workshop, owner's behalf
Date of Request : 29.05.2024
Date of Accident : 24.05.2024
Date of Inspection : 29.05.2024
Inspected at : HC Auto Pte. Ltd.
160 Sin Ming Drive, Sin Ming Auto City
#05-09, Singapore 575722

VEHICLE DETAILS

Vehicle No.	: XE 2917 G	Make & Model	: Volvo FMX370
Year Make	: 2017	Colour	: Blue
Engine No.	: D11400325	Chassis No.	: YV2X1E1D3HB805510
Engine Capacity	: 10,837 cc	Mileage	: 344,974 km
Air-Con	: Yes	Radio/CD/Cassette	: Yes
Seat Belt	: Yes	Rims	: Standard

GENERAL CONDITION OF VEHICLE

General Condition	: Good	Modification	: Nil
Brakes	: Serviceable	Handbrake	: Serviceable
Steering	: Serviceable		

<u>Tyres</u>	<u>Make</u>	<u>Size</u>	<u>Rim</u>	<u>Tread Balance</u>
Front Right	Sailmax	315/80 R22.5	Standard	8 mm
Front Left	Sailmax	315/80 R22.5	Standard	8 mm
Rear Right	GoodYear	315/80 R22.5	Standard	20 mm
Rear Left	GoodYear	315/80 R22.5	Standard	20 mm

ASSESSMENT

	<u>Repairer's Estimate</u>	<u>Recommendation</u>
Spare Parts	: \$ 9,179.51	\$ 6,686.33
Labour Charges	: \$ 4,120.00	\$ 2,000.00
Paint Work	: \$ 2,200.00	\$ 1,600.00
Towing Charges	: \$ -	\$ -
Total	: <u>\$ 15,499.51</u>	<u>\$ 10,286.33</u>
Recommend lump sum repairs	: \$ 8,230.00	
Reduction	: <u>\$ 7,269.51</u>	
Estimated Period Required for Repair	: <u>6 days</u>	



RW AUTOMOTIVE APPRAISERS SERVICES
(Licensed Appraisers Claims Adjusters)
256 Bishan St. 22 #12-472 Singapore 570256
Tel +65 6996 9988 Hp: +65 8338 9988
Email: rw9988@yahoo.com Reg. 52821270B

Page : 1

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vehicle No: XE 2917 G

Report No.: RW/0016/24TP

<u>S/No</u>	<u>QTY</u>	<u>Description</u>	<u>Condition/ Remarks</u>	<u>Repairer's Estimates</u>	<u>My Recommendation</u>
-------------	------------	--------------------	-------------------------------	---------------------------------	------------------------------

REPLACEMENT OF DAMAGED PARTS

1)	1	Front bumper bottom LH	Dented	\$ 1,280.00	N	\$ 1,280.00
2)	1	Front bumper side garnish LH	Cut	\$ 340.62	N	\$ 340.62
3)	1	Front door LH	Dented	\$ 3,844.00	N	\$ 3,844.00
4)	1	Front door outer handle LH	Cut	\$ 620.30	N	\$ 620.30
5)	1	Side panel LH	Repairable	\$ 1,557.20	N	\$ -
6)	1	Side panel '370' LH	Necessary	\$ 128.00	N	\$ 128.00
7)	1	Side panel 'EURO 5' LH	Necessary	\$ 95.00	N	\$ 95.00
8)	1	Rear pillar LH	Repairable	\$ 568.00	N	\$ -
9)	1	Side guard LH	Dented	\$ 988.00	N	\$ 988.00
10)	1	Rear fender LH	Repairable	\$ 645.00	N	\$ -
				\$ 10,066.12		\$ 7,295.92
Less 10%				\$ 1,006.61		\$ 729.59
				\$ 9,059.51		\$ 6,566.33

11)	1	Front door sticker LH	Necessary	\$ 120.00	SN	\$ 120.00
Total (Parts):				\$ 9,179.51		\$ 6,686.33

LABOUR CHARGES

12)	Labour charges.	\$	3,800.00	\$	1,800.00
13)	Re-seal anti rust.	\$	200.00	\$	150.00
14)	To check wiring.	\$	120.00	\$	50.00
15)	To putty and re-spray painting.	\$	2,200.00	\$	1,600.00
Total (Labour):		\$	6,320.00	\$	3,600.00
Total:		\$	15,499.51	\$	10,286.33



RW AUTOMOTIVE APPRAISERS SERVICES
(Licensed Appraisers Claims Adjusters)
256 Bishan St. 22 #12-472 Singapore 570256
Tel +65 6996 9988 Hp: +65 8338 9988
Email: rw9988@yahoo.com Reg. 52821270B

Page : 2

Vehicle No: XE 2917 G

Report No.: RW/0016/24TP

POINT OF IMPACT

Along the left side of the vehicle.

RECOMMENDATION

The vehicle was inspected thoroughly based on the repairer's estimate against the actual damages found on the vehicle. My findings and recommendation are listed as per attached.

My adjusted amount for the cost of repair is **\$10,286.33.**

CONCLUSION

The repairer has agreed to undertake repairs at a lump sum of **\$8,230.00** corresponding to labour charges, spray painting and replacement of parts.

SURVEYED WITHOUT PREJUDICE

RICHARD WONG
(Licensed Appraiser)