

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/AIG24100141/AMA3Q2
Date: 20/11/2025

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7990000060
Claimant Vehicle No : SNF2655A **Insured Vehicle No :** SNP8839U
Date of Loss: 04/10/2024 Nature of Claim: TP Claim No: 9747044289SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNF2655A**
Make & Model: TOYOTA YARIS CROSS, 1.5 XB CVT (A) Engine No: M15AY234200
Reg. Date: 17/03/2022 (Man. Year: 2021) Chassis No: MXPB102014894
Colour: Gold Odometer: 69784 km
Engine Capacity: 1490 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/65 R16 Rear Tyre Size: 205/65 R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,553.45	9,680.92	5,872.53	37.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,960.00	2,250.00	2,710.00	54.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,513.45	11,930.92	8,582.53	41.84
Approved Total (Overridden) (S\$)		9,500.00		
Nett Amount (S\$)	20,513.45	9,500.00	11,013.45	53.69
+ Car Rental (8.0 x S\$100.00/day) (S\$)		800.00		
Nett Liability (S\$)		10,300.00		
Global Sum Settlement (S\$)		10,300.00		

INSPECTION

Date of Assignment: 07/10/2024
Date Inspected: 07/10/2024 Inspected At: Ms Car Auto Pte Ltd (HQ)
8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT
Singapore 415875
Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (UPPER)	Deformed	874.80 FL	*874.80 FL
2	1		*REAR BUMPER (LOWER)	Deformed	678.90 FL	*678.90 FL
3	2		*REAR BUMPER REFLECTOR	Not Necessary	130.20 FL	*- FL
4	2		*REAR BUMPER SIDE RETAINER	Not Necessary	197.00 FL	*- FL
5	1		*TAILGATE	Dented	2,175.40 FL	*1,795.00 FL
6	2		*TAILGATE LAMP	Cracked	999.20 FL	*999.20 FL
7	1		*TAILGATE CENTER REFLECTOR	Cracked	575.10 FL	*575.10 FL
8	1		*TAILGATE INNER HOLDER	Not Necessary	45.70 FL	*- FL
9	1		*TAILGATE LOGO	Necessary	85.50 FL	*85.50 FL
10	1		*TAILGATE EMBLEM YARIS	Necessary	75.20 FL	*75.20 FL
11	1		*TAILGATE EMBLEM CROSS	Necessary	76.80 FL	*76.80 FL
12	2		*TAILGATE STOPPER	Not Necessary	49.80 FL	*- FL
13	1		*TAILGATE TOP LOCK	Damaged	490.70 FL	*490.70 FL
14	1		*TAILGATE LOWER LOCK	Not Necessary	68.00 FL	*- FL
15	1		*TAILGATE INNER TRIM	Cracked	481.60 FL	*481.60 FL
16	1		*TAILGATE CONNECTOR	Not Necessary	286.10 FL	*- FL
17	1		*TAILGATE CONNECTOR WIRE HARNESS	Not Necessary	355.20 FL	*- FL
18	1		*TAILGATE WEATHERSTRIP	Cut	419.10 FL	*419.10 FL
19	1		*SET TAILGATE WINDSCREEN MOULDING	Necessary	191.30 FL	*191.30 FL
20	2		*TAIL LAMP	Cracked	1,381.20 FL	*1,381.20 FL
21	2		*TAIL LAMP LOWER BRACKET	Not Necessary	207.60 FL	*- FL
22	2		*REAR FENDER INNER TRIM	Cracked	1,615.20 FL	*1,615.20 FL
23	2		*REAR FENDER COWLING	Not Necessary	493.40 FL	*- FL
24	2		*REAR FENDER ARCED GARNISH	Cracked	430.80 FL	*430.80 FL
25	1		*REAR END PANEL	Dented	696.70 FL	*696.70 FL
26	1		*REAR END PANEL TOP GARNISH	Deformed	367.50 FL	*367.50 FL
27	1		*REAR END PANEL ANTENNA SENSOR	Cracked	185.40 FL	*185.40 FL
28	1		*REAR FLOOR PANEL	Repair	1,105.70 FL	*- FL
29	1		*REAR FLOOR PANEL CENTRE SPONGE	Not Necessary	217.60 FL	*- FL
30	1		*REAR FLOOR PANEL TOP BOARD	Deformed	687.90 FL	*687.90 FL
31	1		*REAR NUMBER PLATE	Deformed	50.00 FS	*50.00 FS
32	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
33	1		*SET REAR BUMPER LOWER CENTRE GARNISH CLIP	Necessary	50.00 FS	*20.00 FS
34	1		*REAR BUMPER WRAPPING (SPECAIL TYPE)	Not Necessary	800.00 FS	*- FS
35	1		*SET REAR SPOILER CLIP	Not Necessary	80.00 FS	*- FS
36	1		*SET TAIL LAMP CLIP	Not Necessary	30.00 FS	*- FS
37	1		*TAILGATE SEALANT	Not Necessary	150.00 FS	*- FS
38	1		*TAILGATE WRAPPING (SPECAIL TYPE)	Not Necessary	1,200.00 FS	*- FS
39	1		*SET TAILGATE OUTER GARNISH CLIP	Necessary	30.00 FS	*20.00 FS
40	1		*SET TAILGATE INNER TRIM BOARD CLIP	Necessary	50.00 FS	*30.00 FS
41	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
42	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	60.00 FS	*30.00 FS
43	1		*SET REAR FENDER INNER TRIM CLIP	Necessary	80.00 FS	*60.00 FS
44	1		*SET REAR FENDER COWLING CLIP	Not Necessary	80.00 FS	*- FS
45	1		*SET REAR FENDER ARCED GARNISH CLIP	Necessary	50.00 FS	*40.00 FS
46	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*20.00 FS
47	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
48	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS
49	1		*REVERSE CAMERA	Not Necessary	550.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	19,464.60	12,707.90
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,911.15	3,026.98
Total Parts (\$\$)	15,553.45	9,680.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING REMOVAL AND REPLACING PARTS	New	1,800.00	1,000.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	800.00
3	TUFF COAT	New	350.00	60.00
4	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINNING TO FACILITATE REPAIR	New	250.00	60.00
5	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	50.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
7	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
8	TRANSFER TAILGATE MECHANISM	New	150.00	60.00
9	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
10	REMOVE AND REFIX REAR EXHAUST PIPE	New	120.00	0.00
11	REMOVE AND REFIX VIDEO CAMERA	New	80.00	50.00
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS RESET MEMORIES TO SPECIFICATION ETC	New	250.00	0.00
Gross Labour Cost (\$\$)			4,960.00	2,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >