



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SHD 802L

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	BUMPER COVER FRT	BUCKLED/CRACKED	\$747.20	\$747.20
1	BUMPER BRACKET KIT FRT RH	SERVICEABLE	\$101.40	\$0.00
1	BUMPER RETAINER FRT RH	DISTORTED	\$101.40	\$101.40
1	BUMPER FOG LAMP GRILLE RH	SERVICEABLE	\$207.21	\$0.00
1	RADIATOR GRILLE FRAME	SERVICEABLE	\$686.00	\$0.00
1	FRAME FULL SUPPORT PANEL	SERVICEABLE	\$592.70	\$0.00
1	FENDER PANEL FRT RH	BENT	\$437.10	\$437.10
1	FENDER PANEL INNER FRT RH	TO REPAIR SEE LABOUR	\$838.40	\$0.00
1	WHEELARCH FRT RH	DISTORTED	\$191.40	\$191.40
1	WIPER RESERVOIR	SERVICEABLE	\$179.60	\$0.00
1	HEADLAMP RH	MTG CRACKED	\$743.60	\$743.60
	LESS 10.00% DISCOUNT		(\$482.60)	(\$222.07)
			\$4,343.41	\$1,998.63

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER CLIP (SN)	NECESSARY	\$66.00	\$66.00
1	RIM (SN)	DENTED	\$350.00	\$350.00
1	TYRE (80%) (SN)	PUNCTURE	\$300.00	\$240.00
1	FENDER LINER CLIP (SN)	NECESSARY	\$65.00	\$65.00
			\$781.00	\$721.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION		\$3,000.00	\$440.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF FENDER PANEL INNER FRT RH		\$3,000.00	\$400.00
	TO RUST-PROOFING OF THE AFFECTED AREAS		\$170.00	\$30.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT		\$220.00	\$60.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED		\$170.00	\$20.00
			\$6,560.00	\$950.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

GRAND TOTAL		\$11,684.41	\$3,669.63
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		\$2,950.00
Report Ref No: CS/AGI24100142/Knp3m4			

KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.