

GRAND TOTAL

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMJ 1034P

	REPLACEMENT OF PARTS							
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)				
1	FRONT FENDER RH	DENTED	\$1,293.00	\$522.00				
1	FRONT FENDER INNER SHIELD RH	NOT NECESSARY	\$210.00	\$0.00				
1	FRONT HEADLAMP RH	NOT NECESSARY	\$1,765.00	\$0.00				
1	FRONT BUMPER	CRACKED	\$1,640.00	\$633.00				
1	FRONT BUMPER RETAINER RH	NECESSARY	\$194.00	\$76.00				
1	FRONT BUMPER SPONGE	NOT NECESSARY	\$254.00	\$0.00				
1	FRONT BUMPER SIDE COVER RH	NOT NECESSARY	\$342.00	\$0.00				
1	FRONT FOG LAMP COVER RH	NOT NECESSARY	\$313.00	\$0.00				
1	FRONT FOG LAMP RH	NOT NECESSARY	\$493.00	\$0.00				
	LESS 10.00% DISCOUNT		(\$650.40)	(\$123.10)				
			\$5,853.60	\$1,107.90				

Special Nett							
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)			
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	\$50.00	\$40.00			
1	SET FRONT FENDER INNER SHIELD CLIP (SN)	NOT NECESSARY	\$40.00	\$0.00			
1	RIM (SN) (LOCAL REPAIR)	GRAZED	\$800.00	\$100.00			
			\$890.00	\$140.00			

Description of PartsConditionWorkshop Estimate (\$)Our Adjusted (\$)CHECK FRONT WIRING AND LIGHTNING SYSTEM\$100.00\$30.00COMPUTERISED AND CHECK FRONT WHEEL ALIGNMENT\$200.00\$80.00PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS\$1,200.00\$400.00SPRAY PAINTING ON AFFECTED AREAS\$1,000.00\$400.00APPLY ANTI RUST ON AFFECTED AREAS\$100.00\$20.00TO BREAK AND RESEAL FRONT NUMBER PLATE\$200.00\$100.00	Labour							
COMPUTERISED AND CHECK FRONT WHEEL ALIGNMENT \$200.00 \$80.00 PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS \$1,200.00 \$400.00 SPRAY PAINTING ON AFFECTED AREAS \$1,000.00 \$400.00 APPLY ANTI RUST ON AFFECTED AREAS \$100.00 \$20.00	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)				
PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS \$1,200.00 \$400.00 SPRAY PAINTING ON AFFECTED AREAS \$1,000.00 \$400.00 APPLY ANTI RUST ON AFFECTED AREAS \$100.00 \$20.00	CHECK FRONT WIRING AND LIGHTNING SYSTEM		\$100.00	\$30.00				
PARTS \$1,200.00 \$400.00 SPRAY PAINTING ON AFFECTED AREAS \$1,000.00 \$400.00 APPLY ANTI RUST ON AFFECTED AREAS \$100.00 \$20.00	COMPUTERISED AND CHECK FRONT WHEEL ALIGNMENT		\$200.00	\$80.00				
APPLY ANTI RUST ON AFFECTED AREAS \$100.00 \$20.00			\$1,200.00	\$400.00				
\$100.00 \$20.00	SPRAY PAINTING ON AFFECTED AREAS		\$1,000.00	\$400.00				
TO BREAK AND RESEAL FRONT NUMBER PLATE \$200.00	APPLY ANTI RUST ON AFFECTED AREAS		\$100.00	\$20.00				
	TO BREAK AND RESEAL FRONT NUMBER PLATE		\$200.00	\$100.00				
\$2,800.00 \$1,030.00		\$2,800.00	\$1,030.00					

\$9,543.60

\$2,277.90



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

RECOMMENDED COST OF LUMP SUM REPAIRS
(TO ITS PRE-ACCIDENT CONDITION)

\$1,800.00

Report Ref No: CS1/LPM24100144/Enh3

CTY

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.