



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24100154/Aqp3e2
16 RAFFLES QUAY	Date:	04/11/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 1641T	Veh. Inspected	PC 2637U
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24008824MFCT	Excess	\$0.00
Assign From	HARMINDER	Assign Date	08/10/2024

2. Vehicle Details

Make & Model	KING LONG XMQ6117K	C.C	6693
Engine No.	ISBE428521985394	Year of Reg.	14/07/2011
Chassis No.	LA6R1FSH2BB101595	Colour	WHITE
Odometer	- KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	295/80 R22.5	DURATURN	6
L/H Front Tyre	295/80 R22.5	DURATURN	6
R/H Rear Tyre	295/80 R22.5	DURATURN	6
L/H Rear Tyre	295/80 R22.5	DURATURN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/10/2024	Inspection Date	08/10/2024
Survey held at	AUTO UNITED SG PTE LTD 13 KAKI BUKIT ROAD 4, #03-29, BARTLEY BIZ CENTRE, SINGAPORE 417807		

5a. Remarks
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair
ESTIMATED NORMAL PERIOD FOR REPAIR: 18 Working Days