



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24100156/Rvp3m4
16 RAFFLES QUAY	Date:	24/12/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 8566P	Veh. Inspected	SGK 6259R
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24008732MFCT	Excess	\$0.00
Assign From	JOANNE	Assign Date	08/10/2024

2. Vehicle Details

Make & Model	SUBARU IMPREZA 5MT	C.C	1597
Engine No.	EJ16C841166	Year of Reg.	21/08/2006
Chassis No.	JF1GD5KJ36G057177	Colour	BLUE
Odometer	185913 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/45 ZR17	MICHELIN	6
L/H Front Tyre	225/45 ZR17	MICHELIN	6
R/H Rear Tyre	225/45 ZR17	MICHELIN	6
L/H Rear Tyre	225/45 ZR17	MICHELIN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/10/2024	Inspection Date	10/10/2024
Survey held at	SHU FATT AUTO WORKS BLK 1009,BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723		

5a. Remarks
A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS. B)DAMAGES CONSISTENT TO ACCIDENT REPORT. C)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. D)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair
ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days