



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKA 12E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER UPPER	DISTORTED	805.00	805.00
1	REAR BUMPER CENTRE BLACK	TORN	790.00	790.00
1	REAR BUMPER LOWER SILVER	TORN	275.00	275.00
1	REAR BUMPER REFLECTOR N/S	CRACKED	86.00	86.00
1	REAR BUMPER LOWER UNDER COVER	DEFORMED/TORN	390.00	390.00
1	REAR BUMPER LOWER UNDER GARNISH	DEFORMED/TORN	331.00	331.00
1	REAR BUMPER SIDE RETAINER N/S	CRACKED	45.00	45.00
1	REAR BUMPER BEAM	NOT NECESSARY	496.00	-
1	REAR BUMPER LAMP N/S	CRACKED	285.00	285.00
1	REAR BUMPER PDC SENSOR N/S	MALFUNCTION	220.00	220.00
1	REAR BUMPER PDC SENSOR WIRE	SERVICEABLE	292.00	-
1	REAR SIGNAL LAMP N/S	CRACKED	650.00	650.00
1	REAR END PANEL OUTER	DENTED/CRACKED	426.00	426.00
1	TAILLAMP N/S	NOT NECESSARY	947.00	-
1	REAR FENDER OUTER PROTECTOR N/S	DEFORMED/TORN	288.00	288.00
	LESS 10% DISCOUNT		-632.60	-459.10
			5,693.40	4,131.90
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	35.00	35.00
1	REAR LICENCE PLATE (SN)	NOT NECESSARY	50.00	-
			85.00	35.00
<b><u>LABOUR</u></b>				
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REPLACED REAR PDC SENSOR.		80.00	40.00
	TO DISMANTLE & REFIX REAR WINDSCREEN.	NOT NECESSARY	100.00	-
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY.		120.00	80.00
	TO SPRAY RUST PROOFING.		100.00	30.00
	TO DIAGNOSTIC & REPROGRAMME SYSTEM.		250.00	80.00
	LABOUR FOR PANEL BEATING.		900.00	600.00

Report Ref No. CS/INC24100157/Unh3m4(N)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY & SPRAY PAINTING.		1,180.00	800.00
			2,780.00	1,650.00
<b>GRAND TOTAL</b>			<b>8,558.40</b>	<b>5,816.90</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>4,650.00</b>

Report Ref No. CS/INC24100157/Unh3m4(N)

TOTAL FOR SPARE PARTS: \$ 5,778.40 \$ 4,166.90

TOTAL FOR LABOUR : \$ 2,780.00 \$ 1,650.00

TOTAL REPAIR COST: \$ 8,558.40 \$ 5,816.90

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.