



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBC 9559G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR TYRE HUB CAP LH	NOT NECESSARY	288.20	-
1	SLIDING DOOR LH	DENTED	2,860.00	2,360.00
1	REAR FENDER LH (NPA)	TO REPAIR SEE LABOUR	-	-
1	CENTER PANEL LH (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 25% DISCOUNT		-787.05	-590.00
			2,361.15	1,770.00
	<u>SPECIAL NETT ITEMS</u>			
1	SET SLIDING DOOR BOARD CLIP LH (SN)	NOT NECESSARY	50.00	-
			50.00	-
	<u>LABOUR</u>			
	TO REMOVE & REFIX ACCIDENT DAMAGED PARTS & REALIGN ACCIDENT AFFECTED AREA. INCLUSIVE OF THE REPAIR OF REAR FENDER LH AND CENTER PANEL LH.		600.00	300.00
	TO SPRAY PAINT ON ACCIDENT AFFECTED AREA.		800.00	600.00
	TO REMOVE & REFIX DOOR MECHANISM.		60.00	60.00
	TO RUST PROOF AFFECTED AREA.		50.00	30.00
			1,510.00	990.00
GRAND TOTAL			3,921.15	2,760.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				2,200.00

Report Ref No. CS/INC24100159/Avh3m4(N)

TOTAL FOR SPARE PARTS: \$ 2,411.15 \$ 1,770.00

TOTAL FOR LABOUR : \$ 1,510.00 \$ 990.00

TOTAL REPAIR COST: \$ 3,921.15 \$ 2,760.00

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.