



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

Ref: CS/INC24100159/Avh3m4(N)

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

Date: 20/01/2025

ATTN: LIM SERENE

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SNK 4841P	Veh. Inspected	GBC 9559G
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1285293-002	Excess (\$)	0.00
Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	08/10/2024

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HIACE	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	JTFHT02P100119056	Colour	SILVER
Odometer	416827 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195R15C	MICHELIN	6 mm
L/H Front Tyre	195R15C	MICHELIN	6 mm
R/H Rear Tyre	195R15C	MICHELIN	6 mm
L/H Rear Tyre	195R15C	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/07/2024	Inspect Date / Time	08/10/2024 (03:58 PM)
Survey held at	RYDER AUTO PTE LTD 2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days