

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTECICS Limited
10 Eunus Road 8, #09-04A Singapore Post Centre
Singapore 408600**Our File No:** CS/ICS24100166/RTVP3M4
Date: 28/01/2025**REFERENCE**Insured/Claimant: CYCLE & CARRIAGE LEASING PTE LTD Policy No: MCF24B00000800
Date of Loss: 03/10/2024 Nature of Claim: OD Claim No: DMCF2400074H/ST**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SMQ7309X**
Make & Model: KIA CERATO, 1.6 (A) Engine No: G4FGKH737376
Reg. Date: 29/11/2019 (Man. Year: 2018) Chassis No: KNAF1416MK5044613
Colour: White Odometer: 62583 km
Engine Capacity: 1591 cc
Market Value/New Car Price: S\$68,000.00
Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:**CONDITION OF TYRES**Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,758.70	2,227.50	1,531.20	40.74
Miscellaneous Items	290.00	155.00	135.00	46.55
Labour	1,480.00	700.00	780.00	52.70
Paintwork Labour	400.00	200.00	200.00	50.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,928.70	3,282.50	2,646.20	44.63
- Excess (S\$)	0.00	1,000.00	-1,000.00	
(S\$)	5,928.70	2,282.50	3,646.20	61.50
+ GST 9.00/9.00% (S\$)	533.58	205.43	328.15	61.50
Nett Amount (S\$)	6,462.28	2,487.93	3,974.35	61.50

INSPECTIONDate of Assignment: 08/10/2024 Present Location: Diplomat Parts Pte Ltd (HQ)
DIPLOMAT PARTS PTE LTD (HQ)
Date Inspected: 09/10/2024 Inspected At: 209 PANDAN GARDENS
SINGAPORE 609339
Estimated Period of Repair: 5.0 days**Adjuster:** MOHD RASUL**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 28 Jan 2025)
Parts: 143	KIA CERATO 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMQ7309X)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER-FR BUMPER (WCP)	Repair	433.00 F	*- F
2	1		*GRILLE-FRONT BUMPER (WCP)	Cracked	171.00 F	*170.00 F
3	1		*GRILLE ASSY-RADIATOR (WCP)	Not Necessary	189.00 F	*- F
4	1		*GARNISH-RADIATOR GRILLE (WCP)	Not Necessary	33.00 F	*- F
5	1		*ABSORBER-FRONT BUMPER ENERGY (WCP)	Not Necessary	55.00 F	*- F
6	1		*STIFFNER-FR BPR LWR (WCP)	Not Necessary	75.00 F	*- F
7	1		*BEAM COMPLETE-FR BUMPER (WCP)	Bent	324.00 F	*323.00 F
8	1		*CARRIER ASSY-FRONT END MODULE (WCP)	Not Necessary	439.00 F	*- F
9	1		*BLOWER ASSY (WCP)	Cracked	461.00 F	*461.00 F
10	1		*RADIATOR ASSY (WCP)	Bent	510.00 F	*486.00 F
11	1		*CONDENSER ASSY-COOLER (WCP)	Bent	439.00 F	*439.00 F
12	1		*GUARD-AIR,LH (WCP)	Not Necessary	19.00 F	*- F
13	1		*GUARD-AIR,RH (WCP)	Not Necessary	19.00 F	*- F
14	1		*PANEL ASSY-UNDER COVER (WCP)	Not Necessary	99.00 F	*- F
15	1		*DUCT ASSY-EXTENSION (WCP)	Not Necessary	108.00 F	*- F
16	1		*DUCT ASSY-AIR (WCP)	Not Necessary	43.00 F	*- F
17	1		*BEAM COMPLETE-FR BUMPER (WCP)	Repeated	-	*- F
18	1		*BLOWER ASSY (WCP)	Repeated	-	*- F
19	1		*SURER LLC 4L 30% (WCP)	Necessary	-	*7.00 F
20	10		*CLIP (WCP)	Necessary	-	*7.00 F
21	1		*LAMP ASSY-DAY RUNNING LIGHT, RH (WCP)	Cracked	-	*132.00 F

F=Franchise part.

Sub Total (S\$)	3,417.00	2,025.00
+ Margin on L,N Items 10.00/10.00% (S\$)	341.70	202.50
Total Parts (S\$)	3,758.70	2,227.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	SUNDRIES Necessary	20.00	20.00
2	1	SUPPLY COOLANT Not Necessary	100.00	0.00
3	1	SUPPLY NUMBER PLATE Missing	50.00	35.00
4	1	TOP UP A/C GAS Necessary	120.00	100.00
Sub Total (\$\$)			290.00	155.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	SPRAY FRT BUMPER, HOOD	New	400.00	200.00
Labour Items				
2	TOTAL LABOUR PANEL FOR RENEW FRT BUMPER, LWR BUMPER, REPAIR HOOD, AND DAMAGED PARTS	New	660.00	220.00
3	MECHANICAL LABOUR FOR RENEW CONDENSER, RADIATOR AND ETC	New	440.00	220.00
4	CHECK DIAGNOSIS AND ELECTRICAL CHECK	New	220.00	220.00
5	CHECK WIRING	New	80.00	40.00
6	REMOVE AND REFIT SENSOR	New	80.00	0.00
Gross Labour Cost (\$\$)			1,880.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >