10/15/24, 11:17 AM Adjuster Report

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI24100176/TNP3E2

15/10/2024 Date:

**REFERENCE** 

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: ML000183 **Claimant Vehicle** SHC663B Insured Vehicle No: YR854I

No:

Date of Loss: 08/10/2024 Nature of Claim: ΤP Claim No: M2405869

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SHC663B

Make & Model: HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A) G4LEKU298704 Engine No:

Reg. Date: 17/07/2019 (Man. Year: 2019) Chassis No: KMHC851CVKU164900

Colour: Yellow Odometer: 726629 km

**Engine Capacity:** 1580 cc

Market Value/New Car

N/A Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Footbrake (Serviceable): Yes Yes Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Good

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15 Front Left Side: Davanti 6 mm Rear Left Side: Davanti 6 mm Davanti 6 mm Front Right Side: Davanti 6 mm Rear Right Side:

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,632.16	1,316.32	315.84	19.35
Miscellaneous Items	12.00	12.00	0.00	0.00
Labour	820.00	690.00	130.00	15.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,464.16	2,018.32	445.84	18.09
Approved Total (Overridden) (S\$)		1,600.00		
(S\$)	2,464.16	1,600.00	864.16	35.07
+ GST 9.00/9.00% (S\$)	221.77	144.00	77.77	35.07
Nett Amount (S\$)	2,685.93	1,744.00	941.93	35.07

**INSPECTION** 

Date of Assignment: 09/10/2024 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

ComfortDelGro Engineering Pte Ltd (Loyang)

09/10/2024 59 Loyang Drive Date Inspected: Inspected At:

Singapore 508969

Estimated Period of Repair: 2.0 days

MOHD TAUFIKH BIN HAMID Adjuster: Manager: **HUEY YON**  10/15/24, 11:17 AM

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### **REPAIR DETAILS**

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Oct 2024)

Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SHC663B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	459.40 FL	*459.40 FL
2	1		*REAR BUMPER CTR MOULDING	Deformed	451.25 FL	*451.25 FL
3	1		*REAR BUMPER LWR MOULDING	Cut	155.00 FL	*155.00 FL
4	1		*REAR BUMPER REINFORCEMENT	Not Necessary	394.80 FL	*- FL
5	1		*REAR BUMPER FOG LAMP	Cut	201.50 FL	*201.50 FL
6	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
7	1		*REVERSE SENSORS	Cracked	180.00 F	*180.00 F
8	1		*REAR BUMPER MAT	Necessary	50.00 F	*50.00 F
9 E-Er	1	part. L=ListIte	*REAR NO.PLATE WITH TRIM COVER	Cracked	55.00 F	*55.00 F
1 -1 16	ai ici iise	part. L-Listite	IIIDISC.	Sub Total (S\$)	1,968.95	1,574.15
			- List Item Discount	on L Items 20.00/20.00% (S\$)	336.79	257.83
				Total Parts (S\$)	1,632.16	1,316.32
			Report was unsubmitted o	during this print-out.		

# Recommended Miscellaneous Items

No	Qty	Particulars		Repairer's	Amount		
Miscellaneous Items							
1	1	OD/TP Case (Insurer)		12.00	12.00		
			Sub Total (S\$)	12.00	12.00		

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	400.00	380.00
2	SPRAY PAINTING	New	300.00	280.00
3	R/I REVERSE SENSORS	New	120.00	30.00
		Gross Labour Cost (S\$)	820.00	690.00
	Rep	ort was unsubmitted during this print-out.		

< END OF ESTIMATES >