

ASS. REC. BY: Taugh

REF:

CS / TM / 24 / 00 / 76 / 7np3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
	X

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

limits

Veh No: SHC663B Yr Regn: 2019, 67

Type: M.Car / M.Cycle / Bus / Van / Lorry / Tr / Prime Mover /

Truck / Trailer or

Make: Hyundai Lorig c.c. 1580

Colour: Yellow A/C: Insured / Std / NI / NA

Sp. Reading: 726629 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMH C851CV 64 190019

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: NY / S/Rlm / STD A/Rlm or

Tyre Size: F: 195/65R15

R: ^

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westeke

Front: _____ Rear: _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 09/10/24

Survey held at Comfort Loging

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure _____ due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prell. Report

Days Of Repair: _____

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

Lim Tien Siong

TP INSURER:
CCPL

Tokio Marine Insurance Singapore Ltd (HQ)

Singapore

LKK-

WS

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	08/10/2024
Vehicle Reg. No.:	SHC663B	Driveable?	NO
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	17/07/2019
Vehicle Colour:	YELLOW	Gen Condition:	GOOD
Engine No:	G4LEKU298704	Chassis No:	KMHC851CVKU164900
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	1,632.16
Miscellaneous Items	12.00
Labour	820.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,464.16
+ GST 9.00% (S\$)	221.77
Nett Amount (S\$)	2,685.93

This claim is handled by: LIM TIEN SIONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

9/10 @ 08:58hrs

REPAIR DETAILS

Reference

Lim Tien Siong

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Oct 2024)

Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHC663B/09/10/2024 08:58

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	20.00	0.00	de *459.40 FL
2	1		*REAR BUMPER CTR MOULDING	20.00	0.00	de *451.25 FL
3	1		*REAR BUMPER LWR MOULDING	20.00	0.00	at *155.00 FL
4	1		*REAR BUMPER REINFORCEMENT	20.00	0.00	? *394.80 FL
5	1		*REAR BUMPER FOG LAMP	20.00	0.00	at *201.50 FL
6	10		*REAR BUMPER CLIPS	20.00	0.00	we *22.00 FL
7	1		*REVERSE SENSORS	0.00	0.00	at *180.00 F
8	1		*REAR BUMPER MAT	0.00	0.00	at *50.00 F
9	1		*REAR NO.PLATE WITH TRIM COVER	0.00	0.00	cyq *55.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$) 1,968.95

- List Item Discount on L Items (\$\$) 336.79

Total Parts (\$\$) 1,632.16

ComfortDelGro Engineering Pte Ltd/SHC663B/09/10/2024 08:58. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Lim Tian Siong

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer)

12.00

Sub Total (\$\$)

12.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 PANEL BEATING

New

380

400.00

2 SPRAY PAINTING

New

280

300.00

3 R/I REVERSE SENSORS

New

30

120.00

Gross Labour Cost (\$\$)

820.00

ComfortDelGro Engineering Pte Ltd/SHC663B/09/10/2024 08:58. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tan Jiah 9249544
wp' 9/10/24 @ 5pm
2 days
4/5 Mesing after repair
Tan Jiah e/1/1/2024.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) to be resurveyed and is subject to final approval from Insurance Company

Acknowledged by repairer

Signature:

Date/Time: 09.10.2024 08:38

Page : 1

Team: ARC Repair TP(CFSO)1

JOB CARD Sales Order: 5956922

JC NO305606177

STOMER

MS CITYCAB PTE LTD

STOMER NO. 7010070

DRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717

(R) 65551188

(O)

(P)

COUNT CARD NO.

Merimen

REGN NO.:
SHC 663B

MAKE:
HYUNDAI

MODEL:
IONIQ(G2)

YR OF MANU.
17.07.2019

CHASSIS CODE
KMHC851CVKU164900

MILEAGE

FUEL

E.....1/2.....F

DATE/TIME IN
08.10.2024 13:40

TARGET DATE


COMPLETION DATE/TIME:

JOB DESCRIPTION

dent Date: 08.10.2024
RE: 3P 08.10.2024

10 LABOR CODE
PB

DESCRIPTION
LUMPSUM REPAIR-SHC 663B-TP



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

wedgement Slip

Exit Pass

No.: SHC 663B

LIMITS

Vehicle No.:

SHC 663B

of Service Advisor

Signature/Date

Name of Service Advisor

Date

To be kept by Security Guard

returned to Service Reception upon collection