

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No.

19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS	MS FIRST CAPITAL	_ INSURANCE LTD	Ref:	CS/FCI24100177/Knp3m4
	16 RAFFLES QUAY	<i>'</i>	Date:	18/10/2024
	#42-01 HONG LEO		Code:	FCI2
1.	SINGAPORE 04858		:- THIRD PARTY CLA	
••	Insured Veh.	SH 6607T	Veh. Inspected	WD 6483G
	Policy No.	D-24101861MFCT	Coverage	0
	Claim No.	D24008806MFCT	Excess	\$0.00
	Assign From	JOANNE	Assign Date	08/10/2024
2.	Assignition		icle Details	00/10/2024
:	Make & Model	ISUZU CYH52TM (M)	c.c	15681
	Engine No.	6WG1447054	Year of Reg.	28/02/2023
	Chassis No.	JALCYH52TN7000098	Colour	MULTI COLOUR
	Odometer	65495 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: NIL		
3. Conditions of Tyres				
		Size	Make	Balance (mm)
	R/H Front Tyre	295/80R22.5 (D)	AURUNZE	8/8
	L/H Front Tyre	295/80R22.5 (D)	AURUNZE	8/8
	R/H Rear Tyre	295/80R22.5 (D/D)	JOYROAD	6/6/5/5
	L/H Rear Tyre	295/80R22.5 (D/D)	JOYROAD	6/6/5/5
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
	Accident Date	04/10/2024	Inspection Date	11/10/2024
	Survey held at	TSR AUTOMOTIVE PTE LTD 160 SIN MING DRIVE #06-01 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				