

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**India International Insurance Pte Ltd  
6 Raffles Quay, #22-00  
Singapore 048580**Our File No:** CS/III24100178/UNP3E2**Date:** 04/11/2024REFERENCE

Insured/Claimant:	Koh Yok Huat	Policy No:	D22MPC0002323	
Date of Loss:	07/10/2024	Nature of Claim:	OD	Claim No: MPC2024D0011864

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLA7424S</b>		
Make & Model:	HONDA VEZEL, 1.5 (A)	Engine No:	L15B4030579
Reg. Date:	15/03/2016 (Man. Year: 2015)	Chassis No:	RU11110576
Colour:	Blue	Odometer:	133180 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	S\$24,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,654.08	1,215.52	438.56	26.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,570.00	820.00	750.00	47.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,224.08</b>	<b>2,035.52</b>	<b>1,188.56</b>	<b>36.87</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,600.00</b>		
<b>- Excess (S\$)</b>	600.00	600.00	0.00	0.00
<b>Nett Amount (S\$)</b>	<b>2,624.08</b>	<b>1,000.00</b>	<b>1,624.08</b>	<b>61.89</b>

INSPECTION

Date of Assignment:	09/10/2024	
Date Inspected:	10/10/2024	Inspected At: Hup Motor Trading & Service (HQ) Blk 9004 Tampines Street 93, #01-120 Singapore 528838
Estimated Period of Repair:	3.0 days	

**Adjuster:** MARCUS CHUA**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Nov 2024)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLA7424S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	947.30 FL	*947.30 FL
2	10		*FRONT BUMPER CLIPS	Necessary	39.00 FL	*39.00 FL
3	1		*FRONT BUMPER O/S SIDE RETAINER	Not Necessary	29.50 FL	*- FL
4	1		*FRONT BUMPER O/S TOP RETAINER	Not Necessary	48.50 FL	*- FL
5	1		*FRONT O/S FENDER	Repair	431.20 FL	*- FL
6	1		*FRONT O/S FENDER WHEEL GARNISH	Cut	150.60 FL	*150.60 FL
7	10		*FRONT O/S FENDER WHEEL GARNISH CLIPS	Not Necessary	39.00 FL	*- FL
8	1		*FRONT BUMPER LOWER SPOILER SKIRT GARNISH	Grazed	382.50 FL	*382.50 FL
					Sub Total (\$\$)	2,067.60 1,519.40
					- List Item Discount on L Items 20.00/20.00% (\$\$)	413.52 303.88
					Total Parts (\$\$)	1,654.08 1,215.52

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO WIRING CHECK UP FOR AFFECTED WIRING SYSTEM	New	50.00	20.00
2	TO CHECK & ADJUST FRONT WHEEL ALIGNMENT & BALANCING	New	120.00	0.00
3	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS,TO JACK,STRAIGHTEN & KNOCKING OUT FRONT O/S FENDER,FRONT BUMPER REINFORCEMENT & NECESSARY PARTS,TO WELD,REMOVE & ALIGN ABOVE PARTS	New	650.00	300.00
4	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS	New	700.00	500.00
5	TO RESPRAY TUFF-KOTE ON ALL AFFECTED ACCIDENT PARTS	New	50.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,570.00</b>	<b>820.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >