

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	UNITED OVERSEAS INSURANCE LTD		Ref:	CS3/UOI24100182/Enp3e2	
	146 ROBINSON ROAD		Date:	14/10/2024	
	#02-01 UOI BUILDII	NG SINGAPORE 068909	Code:	UOI2	
1.	Policy Particulars :- PRE-REPAIR SURVEY				
	Insured Veh.	YQ 370X	Veh. Inspected	SMR 3001D	
	Policy No.	-	Coverage	0	
	Claim No.	M11D00202410	Excess	\$0.00	
	Assign From	JOEY TAY	Assign Date	09/10/2024	
2.	Vehicle Details				
	Make & Model	TOYOTA CAMRY	C.C	1998	
	Engine No.	1AZE152272	Year of Reg.	01/02/2010	
	Chassis No.	MR053BK4107050880	Colour	BLACK	
	Odometer	201418 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3.	Conditions of Tyres				
		Size	Make	Balance (mm)	
	R/H Front Tyre	215/60 R16	MICHELIN	5	
	L/H Front Tyre	215/60 R16	MICHELIN	5	
	R/H Rear Tyre	215/60 R16	MICHELIN	5	
	L/H Rear Tyre	215/60 R16	MICHELIN	5	
4.	4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
5.	General Information				
	Accident Date	05/10/2024	Inspection Date		
	Survey held at NO. 2 KAKI BUKIT AVENUE 2, #02-02, KAKI BUKIT AUTOHUB SINGAPORE 417921 - REPAIRER: MW BROTHERS AUTO REPAIRS				
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000					

CTY

5b

STEVE CHEN TSUE YEE

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days

Estimate Days of Repair