

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/ICS24100184/RQP3E2**Date:** 15/11/2024REFERENCE

Handling Insurer: ECICS Limited Policy No:

**Claimant Vehicle No :** SGN615U **Insured Vehicle No :** SLC3997X

Date of Loss: 27/09/2024 Nature of Claim: TP Claim No: DMPC2401301H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGN615U**

Make & Model: BMW X2, 1.5 SDRIVE16 MSPT PGR ALED (A) Engine No: F539P760B38A15P

Reg. Date: 23/07/2024 (Man. Year: 2024) Chassis No: WBA32GM0905Z95677

Colour: Grey Odometer: 4747 km

Engine Capacity: 1499 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/45 R21 Rear Tyre Size: 275/45 R21

Front Left Side: Pirelli 7 mm Rear Left Side: Pirelli 7 mm

Front Right Side: Pirelli 7 mm Rear Right Side: Pirelli 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,698.85	2,628.85	70.00	2.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,130.00	3,280.00	850.00	20.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>6,828.85</b>	<b>5,908.85</b>	<b>920.00</b>	<b>13.47</b>
<b>+ GST 9.00/9.00% (\$\$)</b>	614.60	531.80	82.80	13.47
<b>Nett Amount (\$\$)</b>	<b>7,443.45</b>	<b>6,440.65</b>	<b>1,002.80</b>	<b>13.47</b>

INSPECTION

Date of Assignment: 09/10/2024

Date Inspected: 22/10/2024 Inspected At: Performance Motors Limited (HQ)  
303 Alexandra Road, Singapore  
Singapore 159941

Estimated Period of Repair: 3.0 days

**Adjuster:** MOHD RASUL**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Nov 2024)
Parts:	M1-SUV	BMW X2 1.5 SDRIVE16 MSPT PGR ALED (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGN615U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	1		*ALLOY RIM 8JX20 MIDNIGHT GRET	Scratched	2,248.10 FS	*2,248.10 FS
3	1		*FRT LH WHEEL ARCH COVER TRIM MSP GR	Scratched	300.75 FS	*300.75 FS
					Total Parts (\$\$)	2,698.85 2,628.85

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE FRONT LEFT WHEEL ARCH COVER, MAKE GOOD LEFT FRONT FENDER	New	1,700.00	850.00
2	TO RESPRAY LEFT FRONT WHEEL ARCH COVER AND LEFT FRONT FENDER	New	1,628.00	1,628.00
3	TO CHECK ELECTRICAL WIRING SYSTEM	New	177.00	177.00
4	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING (1X)	New	94.00	94.00
5	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT IN ACCORDANCE WITH BMW SPECIFICATIONS. (1X)	New	531.00	531.00
<b>Gross Labour Cost (S\$)</b>			<b>4,130.00</b>	<b>3,280.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >