

ASS. REC. BY:

REF:

TV / 24100107/Ku

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lump Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / RIM or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

: Prell. Report

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S + RS. \$

Fees

Others

Add Fee:

: Site Insp (\$

: Interview (\$

: Tech Invs (\$

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No. 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 I-VP: 9742 6003

001

REPAIR ESTIMATE FOR SMZ22765

No.	Qty	List Items		
1	1	Rear bumper	2980	\$ CM 3,733.00 ✓
2	1	Rear bumper top centre chrome moulding	295	\$ M 702.00 ✓
3	2	Rear bumper top side chrome moulding	0195	\$ Dd 1,190.00 ✓ 390
4	1	Rear bumper centre pad		\$ M 703.00 ✓
5	1	Rear bumper inner cross member		\$ R 550.00 X
6	2	Taillamp		\$ CM 1,020.00 ✓
7	1	Rear boot top centre "MERCEDES" logo		\$ M 55.00 ✓
8	1	Rear boot RH "MERCEDES" emblem		\$ M 118.00 ✓
9	1	Rear boot LH "E220" emblem		\$ M 115.00 ✓
10	1	Rear boot lower key lock panel		\$ R 756.00 X
				\$ 8,942.00
			Less 10%	\$ 894.20
			Total :	\$ 8,047.80

Special Nett Items		
11	1 set Reverse sensor	\$ Sen 280.00 2000

Labour		
1	Labour Charges for remove/refit, panel beating, cutting welding and replacement of damages.	\$ 600.00 3501
2	To putty and spray Spray Paintings charges.	\$ 800.00 600
3	To check wirings and lightings.	\$ 40.00 201
4	To remove, refit, reset reverses sensors.	\$ 80.00 501
5	To apply anti rust treatment	\$ M 50.00 X
Total :		\$ 1,570.00

Total Parts and Labour : \$ 9,897.80

Not witharn
611mp @ 5050h
Purvey After Pain
4 days

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: