

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No. 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 I/P: 9742 6003

REPAIR ESTIMATE FOR SMZ2276S

No.	Qty	List Items		
1	1	Rear bumper <i>2980</i>	<i>Br/cm</i> \$ 3,733.00	✓
2	1	Rear bumper top centre chrome moulding <i>295</i>	\$ <i>na</i> 702.00	✓
3	2	Rear bumper top side chrome moulding <i>0195</i>	\$ <i>na</i> 1,190.00	✓ <i>390</i>
4	1	Rear bumper centre pad	\$ <i>na</i> 703.00	✓
5	1	Rear bumper inner cross member	\$ <i>R</i> 550.00	X
6	2	Taillamp	\$ <i>cm</i> 1,020.00	✓
7	1	Rear boot top centre "MERCEDES" logo	\$ <i>m</i> 55.00	✓
8	1	Rear boot RH "MERCEDES" emblem	\$ <i>m</i> 118.00	✓
9	1	Rear boot LH "E220" emblem	\$ <i>m</i> 115.00	✓
10	1	Rear boot lower key lock panel	\$ <i>n</i> 756.00	X
			\$ 8,942.00	
			Less 10%	\$ 894.20
			Total :	\$ 8,047.80

Special Nett Items		
11	1 set Reverse sensor	\$ <i>sen</i> 280.00 <i>2000</i>

Labour		
1	Labour Charges for remove/refit, panel beating, cutting welding and replacement of damages.	\$ 600.00 <i>3501</i>
2	To putty and spray Spray Paintings charges.	\$ 800.00 <i>600</i>
3	To check wirings and lightings.	\$ 40.00 <i>20</i>
4	To remove, refit, reset reverses sensors.	\$ 80.00 <i>50</i>
5	To apply anti rust treatment	\$ <i>na</i> 50.00 X
Total :		\$ 1,570.00

Total Parts and Labour : \$ 9,897.80

Not Authorised
61Ry @ 5050h
Recovery After Pain
4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: