



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: JULIE MANGUBAT

Ref: CS/INC24100190/Avh3e2(N)

Date: 23/01/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGX 9919G	Veh. Inspected	SJL 6704G
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1298623-002	Excess (\$)	0.00
Assign From	JULIE MANGUBAT	Assign Date	10/10/2024

2. Vehicle Particulars & Condition

Make & Model	HONDA JAZZ	c.c	1339
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	JHMGE68509S209858	Colour	WHITE
Odometer	224444 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/50 R16	BRIDGESTONE	6 mm
L/H Front Tyre	205/50 R16	BRIDGESTONE	6 mm
R/H Rear Tyre	205/50 R16	BRIDGESTONE	6 mm
L/H Rear Tyre	205/50 R16	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/10/2024	Inspect Date / Time	17/10/2024 (01:47 PM)
Survey held at	TSL AUTO PRO SELECTION PTE LTD BLK 1 KAKI BUKIT AVENUE 6 #01-06 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**