



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)	Ref:	CS3/SPF24100192/Evp3e2
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE)	Date:	14/10/2024
POLICE LOGISTICS BASE (PLB)	Code:	SPF
1 HEMMANT ROAD SINGAPORE 438675		

1. Policy Particulars :- PRE-REPAIR SURVEY

Insured Veh.	QX 76D	Veh. Inspected	SJJ 1220D
Policy No.	-	Coverage	0
Claim No.	ACS/105/009/2024/055 (CF)	Excess	\$0.00
Assign From	LAI PENGCHONG	Assign Date	09/10/2024

2. Vehicle Details

Make & Model	TOYOTA RUSH	C.C	1495
Engine No.	3SZ1967005	Year of Reg.	01/09/2008
Chassis No.	J200E0017969	Colour	WHITE
Odometer	210900 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	215/60 R17	TOYO	5
L/H Front Tyre	215/60 R17	TOYO	5
R/H Rear Tyre	215/60 R17	TOYO	5
L/H Rear Tyre	215/60 R17	TOYO	5

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	04/10/2024	Inspection Date	10/10/2024 (12:22)
Survey held at	STK AUTO (S) PTE LTD 8 KAKI BUKIT AVE 4 #03-21 PREMIER@KAKI BUKIT SSINGAPORE 415875		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 9 Working Days