



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)	Ref:	CS3/SPF24100192/Evp3e2
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE)	Date:	14/10/2024
POLICE LOGISTICS BASE (PLB)	Code:	SPF
1 HEMMANT ROAD SINGAPORE 438675		

### 1. Policy Particulars :- PRE-REPAIR SURVEY

<b>Insured Veh.</b>	QX 76D	<b>Veh. Inspected</b>	SJJ 1220D
<b>Policy No.</b>	-	<b>Coverage</b>	0
<b>Claim No.</b>	ACS/105/009/2024/055 (CF)	<b>Excess</b>	\$0.00
<b>Assign From</b>	LAI PENGCHONG	<b>Assign Date</b>	09/10/2024

### 2. Vehicle Details

<b>Make &amp; Model</b>	TOYOTA RUSH	<b>C.C</b>	1495
<b>Engine No.</b>	3SZ1967005	<b>Year of Reg.</b>	01/09/2008
<b>Chassis No.</b>	J200E0017969	<b>Colour</b>	WHITE
<b>Odometer</b>	210900 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>General</b>	FAIR
<b>Modification(s)</b>	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	215/60 R17	TOYO	5
L/H Front Tyre	215/60 R17	TOYO	5
R/H Rear Tyre	215/60 R17	TOYO	5
L/H Rear Tyre	215/60 R17	TOYO	5

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	04/10/2024	<b>Inspection Date</b>	10/10/2024 (12:22)
<b>Survey held at</b>	STK AUTO (S) PTE LTD - 8 KAKI BUKIT AVE 4 #03-21 PREMIER@KAKI BUKIT SINGAPORE 415875		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.  
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 9 Working Days