

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	INCOME INSURAN	ICE LTD	Ref:	CS/INC24100195/Uvh3e2	
	75 BRAS BASAH R		Date:	30/10/2024	
	INCOME CENTRE	SINGAPORE 189557	Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMC 5962X	Veh. Inspected	GBH 7749L	
	Policy No.	-	Coverage	0	
	Claim No.	MT/1298912-001	Excess	\$0.00	
	Assign From	EILEEN LEE	Assign Date	10/10/2024	
2.	2. Vehicle Details				
	Make & Model	TOYOTA HIACE DX 2.8 (A)	C.C	2754	
	Engine No.	1GD8314429	Year of Reg.	26/09/2018	
	Chassis No.	GDH2012002184	Colour	SILVER	
	Odometer	167947 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: NIL			
3.	3. Conditions of Tyres				
		Size	Make	Balance (mm)	
	R/H Front Tyre	195R15	YOKOHAMA	6	
	L/H Front Tyre	195R15	YOKOHAMA	6	
	R/H Rear Tyre	195R15	BRIDGESTONE	6	
	L/H Rear Tyre	195R15	BRIDGESTONE	6	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR AND REAR O/S PORTION.					
DAMAGES SEE DETAILS.					
5.	5. General Information				
	Accident Date	07/10/2024	Inspection Date	15/10/2024 (11:12)	
	Survey held at	urvey held at BLUWEL AUTOMOTIVE SERVICE PL - BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883			
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair					

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days