

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG24060209/AVP3M4**Date:** 01/08/2024REFERENCE

Insured/Claimant:	LEE XINGYONG	Policy No:	7220020096	
Date of Loss:	21/06/2024	Nature of Claim:	OD	Claim No: 1993981680SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKB4006S		
Make & Model:	AUDI A5 SPORTBACK, 2.0 TFSI S TRONIC (110 KW) (A)	Engine No:	DEM035997
Reg. Date:	25/02/2022 (Man. Year: 2021)	Chassis No:	WAUZZZF56NA010731
Colour:	Black	Odometer:	52606 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$186,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40R18	Rear Tyre Size:	245/40R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,455.00	8,732.56	19,722.44	69.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,152.00	2,872.00	3,280.00	53.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	34,607.00	11,604.56	23,002.44	66.47
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	33,807.00	10,804.56	23,002.44	68.04
+ GST 9.00/9.00% (S\$)	3,042.63	972.41	2,070.22	68.04
Nett Amount (S\$)	36,849.63	11,776.97	25,072.66	68.04

INSPECTION

Date of Assignment:	26/06/2024	
Date Inspected:	24/06/2024	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,802.00 FS	*2,241.60 FS
2	2		*FRONT BUMPER SECURING STRIP	Not Necessary	90.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	245.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	329.00 FS	*- FS
5	1		*FRONT BUMPER SPOILER	Not Necessary	675.00 FS	*- FS
6	2		*FRONT BUMPER AIR GUIDE - LH / RH	Not Necessary	112.00 FS	*- FS
7	1		*FRONT BUMPER CLOSING ELEMENT	Cracked	329.00 FS	*262.80 FS
8	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Not Necessary	338.00 FS	*- FS
9	2		*FRONT BUMPER TRIM - LH / RH	Not Necessary	120.00 FS	*- FS
10	1		*FRONT BUMPER TRIM - CENTER	Not Necessary	143.00 FS	*- FS
11	1		*RADIATOR GRILLE	Cracked	2,098.00 FS	*1,678.40 FS
12	1		*360 CAMERA	Not Necessary	1,353.00 FS	*- FS
13	1		*360 CAMERA BRACKET	Not Necessary	24.00 FS	*- FS
14	1		*360 CAMERA SECURING PLATE	Not Necessary	18.00 FS	*- FS
15	1		*360 CAMERA CAP	Missing	158.00 FS	*126.00 FS
16	2		*FRONT PARKING AID SENSOR	Not Necessary	572.00 FS	*- FS
17	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	11.00 FS	*- FS
18	1		*FRONT BUMPER TOP COVER	Deformed	160.00 FS	*127.60 FS
19	1		*CAUTION SIGN	Necessary	25.00 FS	*19.44 FS
20	1		*A/C STICKER	Necessary	10.00 FS	*7.52 FS
21	1		*LOCK CARRIER BRACKET	Damaged	173.00 FS	*138.00 FS
22	1		*FRONT REINFORCEMENT BEAM	Dented	1,033.00 FS	*826.40 FS
23	2		*FRONT REINFORCEMENT BEAM BRACKET - LH / RH	Not Necessary	572.00 FS	*- FS
24	1		*FRONT FOAM FILLER PIECE	Cracked	183.00 FS	*146.40 FS
25	1		*OUTSIDE TEMP SENSOR BRACKET	Necessary	30.00 FS	*24.00 FS
26	2		*LOCK CARRIER BRACKET SUPPORT - LH / RH	Damaged	74.00 FS	*57.52 FS
27	1		*LED HEADLIGHT - LH	Not Necessary	9,204.00 FS	*- FS
28	3		*LED HEADLIGHT SPACER - LH	Not Necessary	150.00 FS	*- FS
29	1		*LIFT CYLINDER - LH	Not Necessary	238.00 FS	*- FS
30	1		*LIFT CYLINDER BRACKET - LH	Not Necessary	19.00 FS	*- FS
31	1		*LIFT CYLINDER HOSE	Not Necessary	118.00 FS	*- FS
32	1		*BONNET	Dented	3,538.00 FS	*2,830.40 FS
33	1		*BONNET ATTACHMENT PARTS	Not Necessary	138.00 FS	*- FS
34	2		*BONNET HINGE - LH / RH	Not Necessary	1,020.00 FS	*- FS
35	1		*BONNET IMPACT PROTECTION - CENTER	Necessary	36.00 FS	*28.40 FS
36	2		*BONNET IMPACT PROTECTION - LH / RH	Necessary	72.00 FS	*56.24 FS
37	1		*BONNET SOUND ABSORBER	Not Necessary	431.00 FS	*- FS
38	1		*FRONT FENDER TOP COVER - LH	Not Necessary	90.00 FS	*- FS
39	1		*FRONT FENDER LEDGE COVER - LONG	Not Necessary	45.00 FS	*- FS
40	1		*FRONT FENDER LEDGE COVER - SHORT	Not Necessary	55.00 FS	*- FS
41	1		*BONNET STRIKER - LH / RH	Not Necessary	126.00 FS	*- FS
42	2		*BONNET LID LOCK	Not Necessary	491.00 FS	*- FS
43	1		*BONNET BOWDEN CABLE - CENTER	Damaged	71.00 FS	*56.40 FS
44	1		*BONNET BOWDEN CABLE COVER - CENTER	Not Necessary	12.00 FS	*- FS
45	1		*BONNET BOWDEN CABLE - CENTER	Not Necessary	71.00 FS	*- FS
46	1		*BONNET LOCK CABLE	Not Necessary	92.00 FS	*- FS
47	2		*RADIATOR AIR GUIDE - LH / RH	Not Necessary	80.00 FS	*- FS
48	2		*RADIATOR AIR GUIDE - LH / RH	Deformed	54.00 FS	*42.24 FS
49	1		*RADIATOR AIR GUIDE - UPPER	Not Necessary	27.00 FS	*- FS
50	1		*RADIATOR AIR GUIDE - LOWER	Not Necessary	40.00 FS	*- FS
51	1		*SUNDRIES	Necessary	500.00 FS	*3.20 FS
52	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$) **28,455.00** **8,732.56**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,400.00	1,000.00
4	TO RESPRAY FRONT BUMPER AND BONNET	New	2,100.00	1,100.00
5	TO CARRY OUT CALIBRATION FOR FRONT BUMPER RADAR SENSOR AND DISTANCE REGULATION	New	480.00	0.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
Gross Labour Cost (\$\$)			6,152.00	2,872.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >