

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24100199/KPA3Q2
Date: 06/01/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D18MFL0003414_05
Claimant Vehicle No : SJV8774M Insured Vehicle No : SML5596Y
Date of Loss: 03/10/2024 Nature of Claim: TP Claim No: MFL2024D0011680

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJV8774M
Make & Model: MERCEDES-BENZ CLA180, 1.6 COUPE URBAN (R18 LED) (A) Engine No: 27091031166610
Reg. Date: 28/04/2017 (Man. Year: 2016) Chassis No: WDD1173422N458530
Colour: Metallic Maroon Odometer: 48915 km
Engine Capacity: 1595 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40 R18 Rear Tyre Size: 225/40 R18
Front Left Side: Bridgestone 7 mm Rear Left Side: Bridgestone 7 mm
Front Right Side: Bridgestone 7 mm Rear Right Side: Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,579.00	3,025.00	554.00	15.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,930.00	1,080.00	850.00	44.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,509.00	4,105.00	1,404.00	25.49
Approved Total (Overridden) (S\$)		3,200.00		
(S\$)	5,509.00	3,200.00	2,309.00	41.91
+ GST 9.00/9.00% (S\$)	495.81	288.00	207.81	41.91
Nett Amount (S\$)	6,004.81	3,488.00	2,516.81	41.91
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		33.18		
Nett Liability (S\$)		3,821.18		

INSPECTION

Date of Assignment: 14/10/2024
Date Inspected: 14/10/2024 Inspected At: Optima Werkz Pte Ltd (HQ)
10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK
Autopoint
Singapore 568047
Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Nov 2024)
Parts:	143	MERCEDES-BENZ CLA180 1.6 COUPE URBAN (R18 LED) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJV8774M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RHF DOOR (WCP)	Bent	1,300.00 F	*1,300.00 F
2	1		*RHF WINDOW REGULATOR (WCP)	Serviceable	420.00 F	*- F
3	1		*RHR DOOR (WCP)	Bent	1,450.00 F	*1,450.00 F
4	1		*RHS ROCKER PANEL (NPA)	Repair	0.00 F	*- F
5	1		*RR BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
6	1		*SUNDRIES	Not Necessary	42.00 FS	*- FS
					Sub Total (S\$)	3,262.00 2,750.00
					+ Margin on L,N Items 10.00/10.00% (S\$)	317.00 275.00
					Total Parts (S\$)	3,579.00 3,025.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	T REMOVE ,REPLACE ,REPAIR ,READJUST & REFIX RR AFFECTED AREAS	New	800.00	400.00
2	TO PERFORM WIRING CHECKS ON ELECTRICAL SYSTEMS	New	30.00	20.00
3	TO REMOVE PUTTY ,REPAIR SAND AND RESPAY AFFECTED AREAS	New	840.00	660.00
4	TO REMOVE,REPLACE & REFIX BUMPER SENSORS	New	30.00	0.00
5	TO REMOVE REPLACE & REINSTALL BOOTLID INNER MECHANISM	New	30.00	0.00
6	TO PERFORM ADAS CHECKS CALIBRATION & PROGRAMMING	New	200.00	0.00
Gross Labour Cost (\$\$)			1,930.00	1,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >