4/14/25, 9:25 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS24100200/TNP3E2

Date: 14/04/2025

REFERENCE

No:

Handling Insurer: ECICS Limited Policy No: MPC24A00161602

Claimant Vehicle

XD4671G Insured Vehicle No: SKB1018C

Date of Loss: 04/10/2024 Nature of Claim: TP Claim No: DMPC2401359H/02/AF

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: XD4671G

Make & Model: MAN TGM 18.280, 6.9 D 4X2 BB (M) Engine No: 21825185452520

Reg. Date: 01/12/2010 (Man. Year: 2010) Chassis No: WMAN08ZZ7AY244448

Colour: Green Odometer: 0 km

Engine Capacity: 6871 cc

Market Value/New Car Price:

N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5 Rear Tyre Size: 295/80 R22.5 (D)
Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 8/8 mm
Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		15,612.02	15,597.02	15.00	0.10
Miscellaneous Items		0.00	0.00	0.00	
Labour		9,620.00	7,280.00	2,340.00	24.32
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	25,232.02	22,877.02	2,355.00	9.33
	Approved Total (Overridden) (S\$)		17,000.00		
	(S\$)	25,232.02	17,000.00	8,232.02	32.63
	+ GST 9.00/9.00% (S\$)	2,270.88	1,530.00	740.88	32.63
	Nett Amount (S\$)	27,502.90	18,530.00	8,972.90	32.63

INSPECTION

Date of Assignment: 10/10/2024

GOLDBELL ENGINEERING PTE LTD (TUAS) (HQ)

Date Inspected: 05/11/2024 Inspected At: 8 TUAS AVE 18 Singapore 638892

Estimated Period of Repair: 10.0 days

Adjuster: MOHD TAUFIKH BIN HAMID Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

4/14/25, 9:25 AM Adjuster Report

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 14 Apr 2025)

Parts: N/A MAN TGM 18.280 6.9 D 4X2 BB (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for XD4671G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SYNTHETIC BUMPER	Cracked	3,600.00 FL	*3,600.00 FL
2	1		*BUMPER END PANEL RH	Cracked	130.00 FL	*130.00 FL
3	1		*BUMPER END PANEL LH	Missing	130.00 FL	*130.00 FL
4	2		*TRIM	Deformed	260.00 FL	*260.00 FL
5	1		*BUMPER GARNISH LOWER RH	Deformed	338.00 FL	*338.00 FL
6	1		*BUMPER GARNISH LOWER LH	Deformed	338.00 FL	*338.00 FL
7	1		*HEADLAMP RH	Cut	1,690.00 FL	*1,690.00 FL
8	1		*HEADLAMP LH	Cracked	1,690.00 FL	*1,690.00 FL
9	1		*AUXILIARY HEADLAMP FLASHER	Cracked	455.00 FL	*455.00 FL
10	1		*ENTRY MUDGUARD LH	Deformed	2,860.00 FL	*2,860.00 FL
11	1		*STEP, LH	Cracked	455.00 FL	*455.00 FL
12	1		*FLASHER	Distorted	156.00 FL	*156.00 FL
13	1		*WHEEL NUT COVER RING AXLE	Bent	234.00 FL	*234.00 FL
14	1		*WIND DEFLECTOR	Deformed	494.00 FL	*494.00 FL
15	1		*PILLAR LINING	Deformed	585.00 FL	*585.00 FL
16	1		*REAR LAMP RH	Broken	491.40 FL	*491.40 FL
17	1		*REAR LAMP LH	Broken	491.40 FL	*491.40 FL
18	1		*STICKER (NPA)	Necessary	0.00 FS	*-FS
19	1		*NUMBER PLATE	Missing	50.00 FS	*35.00 FS
20	1		*60KM/H	Necessary	30.00 FS	*30.00 FS
21	1		*ENTRY MUDGUARD RH	Deformed	2,860.00 FL	*2,860.00 FL
F=Fra	ınchise	part. S=SpcNe	tt. L=ListItemDisc.			
				Sub Total (S\$)	17,337.80	17,322.80
	- List Item Discount on L Items 10.0		0.00/10.00% (S\$)	1,725.78	1,725.78	
				Total Parts (S\$)	15,612.02	15,597.02

Report was unsubmitted during this print-out.

Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC	New	2,500.00	2,100.00
2	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC	New	1,800.00	1,400.00
3	TO CHECK FOR AND RECTIFY WIRING FAULTS	New	280.00	180.00
4	TO DISMANTLE AND CHANGE NEW 1 PC REAR UNDERRUN BUMPER (NPA)	New	0.00	0.00
5	TO DISMANTLE AND CHANGE NEW 2 PCS REAR ALUMINIUM SHEET (NPA)	New	0.00	0.00
6	REAR LEFT HAND SIDE POLE DENTED, TO PROVIDE LABOUR TO PULL IT BACK WITH REPAIR WORK (NPA)	New	0.00	0.00
7	TOTAL LABOUR FOR REAR DECK	New	5,040.00	3,600.00
	Gross Labou	r Cost (S\$)	9,620.00	7,280.00
	Report was unsubmitted during this pr	int-out.		

< END OF ESTIMATES >