

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 11 Nov 2024

Preliminary Advice

Insured Vehicle No	: SKB1018C		
TP Vehicle No	: XD4671G	Accident Date	: 04/10/2024
Make	: MAN TGM 18.280	Assignment Date	: 10/10/2024
Date of Inspection	: 05/11/2024	Est. Duration of Repair	: 10
Inspection At	: GOLDBELL ENGINEERING PTE LTD (TUAS) (HQ) 8 TUAS AVE 18 SINGAPORE 638892		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	25,232.02
Revised Amount	:S\$	12,733.12
Check Items (Estimated)	:S\$	7,569.90
Total	:S\$	20,303.02
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	20,000.00
COE / PARF Rebate	:S\$	2,702.00
Salvage Value	:S\$	
Margin for Repair	:S\$	17,298.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Repairer able to repair the vehicle not more than \$17,000.00.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.