

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24100202/UMA3Q2  
Date: 07/02/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D23MFL0002571\_01  
Claimant Vehicle No : SMZ883C Insured Vehicle No : SLK5264Y  
Date of Loss: 02/10/2024 Nature of Claim: TP Claim No: MFL2024D0011662

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMZ883C  
Make & Model: NISSAN NOTE E-POWER, 1.2 L PREMIUM (A) Engine No: HR12042210L  
Reg. Date: 18/02/2022 (Man. Year: 2021) Chassis No: JN1FAAE13Z0900958  
Colour: Blue Odometer: 71556 km  
Engine Capacity: 1198 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R16 Rear Tyre Size: 185/60 R16  
Front Left Side: Yokohama 7 mm Rear Left Side: Yokohama 7 mm  
Front Right Side: Yokohama 7 mm Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,968.74	2,194.34	774.40	26.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,018.00	1,863.00	1,155.00	38.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,986.74	4,057.34	1,929.40	32.23
+ GST 9.00/9.00% (S\$)	538.81	365.16	173.65	32.23
Nett Amount (S\$)	6,525.55	4,422.50	2,103.05	32.23
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		4,649.75		

INSPECTION

Date of Assignment: 21/10/2024  
Date Inspected: 21/10/2024 Inspected At: Autolution Industrial Pte Ltd (Ubi)  
19 Ubi Road 4  
Singapore 408623  
Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA Manager: Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Jan 2025)
Parts:	144	NISSAN NOTE E-POWER 1.2 L PREMIUM (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMZ883C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS
2	1		*REAR LICENCE PLATE	Scratched	60.00 FS	*60.00 FS
3	1		*REVERSE SENSOR BRACKET CORNER LH	Necessary	41.90 FS	*41.90 FS
4	2		*REVERSE SENSOR BRACKET CENTRE	Necessary	83.80 FS	*83.80 FS
5	1		*REAR W/SCREEN SEALANT	Necessary	80.00 FS	*80.00 FS
6	1		*EMBLEM REAR E-POWER	Necessary	36.40 FN	*36.40 FN
7	1		*REAR EMBLEM NOTE	Necessary	88.80 FN	*88.80 FN
8	1		*TAIL GATE BACK DOOR LOCK	Not Necessary	142.80 FN	*- FN
9	1		*STRIKER -TAIL GATE	Not Necessary	38.70 FN	*- FN
10	1		*BACK DOOR W/STRIP	Not Necessary	106.30 FN	*- FN
11	1		*REAR W/SCREEN FASTENER	Necessary	71.00 FN	*71.00 FN
12	1		*REAR W/SCREEN MOULDING	Necessary	251.90 FN	*251.90 FN
13	1		*TAIL GATE BACK DOOR	Dented	1,352.80 FN	*1,352.80 FN
14	1		*ENERGY ABSORBER REAR BUMPER	Not Necessary	153.60 FN	*- FN
15	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	31.40 FN	*- FN
16	1		*REAR BUMPER FASCIA LH	Not Necessary	196.90 FN	*- FN
17	2		*REAR BUMPER STAY	Not Necessary	216.00 FN	*- FN
18	1		*REAR BUMPER SIDE BRKT LH	Not Necessary	19.80 FN	*- FN
19	20		*CLIP REAR BUMPER	Necessary	30.00 FN	*30.00 FN
20	1		*REAR BUMPER FASCIA	Cut	579.90 FN	*579.90 FN

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	3,632.00	2,676.50
- Nett Item Discount on N Items 20.00/20.00% (S\$)	663.26	482.16
Total Parts (S\$)	2,968.74	2,194.34

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR CHARGES TO REPAIR REAR PANEL ,RENEW REAR BUMPER AND TAIL GATE BAKK DOOR	New	1,200.00	645.00
2	CHARGES TO SPRAY PAINTING SAME	New	1,300.00	700.00
3	REMOVE AND REVERSE SENSOR AND RESET	New	110.00	110.00
4	REMOVE AND INSTALL REAR W/SCREEN GLASS	New	180.00	180.00
5	REMOVE AND INSTALL TAIL GATE BACK DOOR MECHANISM	New	80.00	80.00
6	APPLY SEALANT TO TAIL GATE BACK DOOR	New	100.00	100.00
7	CHECK LIGHT SYSTEM	New	48.00	48.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,018.00</b>	<b>1,863.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >