

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24100203/AMA3Q2
Date: 28/03/2025**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800016732
Claimant Vehicle No :	SKS8913H	Insured Vehicle No :	SLW5564T
Date of Loss:	10/10/2024	Nature of Claim:	TP
		Claim No:	4467107819SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKS8913H	Engine No:	A8230973N20B20B
Make & Model:	BMW 420I, 2.0 Gran Coupe (A)	Chassis No:	WBA4A12030GK06189
Reg. Date:	13/05/2015 (Man. Year: 2014)	Odometer:	137964 km
Colour:	Silver		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,309.53	2,665.75	1,643.78	38.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,380.00	450.00	1,930.00	81.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,689.53	3,115.75	3,573.78	53.42
Approved Total (Overridden) (S\$)		2,500.00		
(S\$)	6,689.53	2,500.00	4,189.53	62.63
+ GST 9.00/9.00% (S\$)	602.06	225.00	377.06	62.63
Nett Amount (S\$)	7,291.59	2,725.00	4,566.59	62.63
+ Loss of Use (2.0 x S\$100.00/day) (S\$)		200.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		2,952.25		
Global Sum Settlement (S\$)		2,950.00		

INSPECTION

Date of Assignment:	14/10/2024	Chia Auto Services Pte Ltd (HQ) 23 Kaki Bukit Ave 4, #04-01 Vicom Inspection Center Singapore 415933
Date Inspected:	14/10/2024 Inspected At:	
Estimated Period of Repair:	2.0 days	

Adjuster: ADRIAN LING**Manager:** Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,955.30 FL	*1,650.00 FL
2	2		*REAR BUMPER SIDE RETAINER	Not Necessary	300.00 FL	*- FL
3	1		*REAR BUMPER CENTER OUTER GARNISH	Cut	520.00 FL	*195.00 FL
4	2		*REAR BUMPER SENSOR	Not Necessary	560.00 FL	*- FL
5	1		*REAR BUMPER TOWING COVER	Not Necessary	80.00 FL	*- FL
6	1		*REAR BUMPER CENTRE GARNISH	Cracked	250.00 FL	*250.00 FL
7	1		*REAR BUMPER REINFORCEMENT	Dented	850.00 FL	*690.00 FL
8	1		*SET REAR BUMPER CLIPS	Necessary	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,535.30	2,805.00
- List Item Discount on L Items 5.00/5.00% (S\$)	225.77	139.25
Total Parts (S\$)	4,309.53	2,665.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,000.00	200.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,000.00	200.00
3	TUFF COAT	New	200.00	0.00
4	WIRING CHECK	New	80.00	0.00
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	100.00	50.00
			Gross Labour Cost (\$\$)	450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >