



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNK 8113G

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BONNET	TO REPAIR SEE LABOUR	\$885.00	\$0.00
2	FRONT BONNET HINGE @\$181.50	TO REPAIR SEE LABOUR	\$363.00	\$0.00
1	FRONT RH HEADLAMP	MTG CRACKED	\$1,650.00	\$1,650.00
1	FRONT CENTRE GRILLE	SERVICEABLE	\$481.50	\$0.00
1	FRONT "TOYOTA" LOGO	NOT NECESSARY	\$98.50	\$0.00
1	FRONT BUMPER	BENT	\$1,150.00	\$1,150.00
2	FRONT BUMPER SIDE RETAINER @\$121.50	CRACKED	\$243.00	\$243.00
10	FRONT BUMPER CLIP @\$5.00	NECESSARY	\$50.00	\$50.00
1	FRONT BUMPER GRILLE	CRACKED	\$485.20	\$485.20
1	FRONT BUMPER RH FOG LAMP	SERVICEABLE	\$381.50	\$0.00
1	FRONT BUMPER RH FOG LAMP GARNISH	DENTED	\$280.50	\$280.50
1	FRONT BUMPER RH SIDE LAMP	SERVICEABLE	\$321.20	\$0.00
1	FRONT BUMPER RH PARKING SENSOR	DENTED	\$280.50	\$280.50
1	FRONT BUMPER RH PARKING SENSOR BASE	SERVICEABLE	\$121.50	\$0.00
1	FRONT BUMPER LOWER	CRACKED	\$481.50	\$481.50
1	FRONT BUMPER REINFORCEMENT	BENT	\$381.50	\$381.50
1	FRONT SUPPORT TOP PANEL	TO REPAIR SEE LABOUR	\$381.50	\$0.00
1	FRONT SUPPORT RH SIDE PANEL	TO REPAIR SEE LABOUR	\$321.20	\$0.00
1	FRONT SUPPORT RH SIDE BAR	TO REPAIR SEE LABOUR	\$181.50	\$0.00
1	FRONT RADIATOR TOP PANEL	TO REPAIR SEE LABOUR	\$380.50	\$0.00
1	FRONT RADIATOR LOWER PANEL	CRACKED	\$481.50	\$481.50
1	FRONT RH HORN	SERVICEABLE	\$121.20	\$0.00
1	FRONT RH FENDER	BUCKLED	\$681.50	\$681.50
1	FRONT RH FENDER PROTECTOR	BUCKLED	\$280.20	\$280.20
1	FRONT RH FENDER INNER SHIELD	CRACKED	\$181.20	\$181.20
10	FRONT RH FENDER INNER SHIELD CLIP @\$5.00	NECESSARY	\$50.00	\$50.00
1	FRONT RH FENDER INNER BRACKET	TO REPAIR SEE LABOUR	\$121.50	\$0.00
	LESS 25.00% DISCOUNT		(\$2,709.05)	(\$1,669.15)
			\$8,127.15	\$5,007.45



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT NUMBER PLATE CASING (SN)	CRACKED	\$40.00	\$35.00
1	SET PAINT PROTECTION FILM (SN)	NECESSARY	\$900.00	\$300.00
			\$940.00	\$335.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	WIRING		\$80.00	\$20.00
	TUFF KOTE		\$80.00	\$30.00
	SPRAY PAINTING		\$1,400.00	\$800.00
	LABOUR CHARGES. INCLUSIVE OF THE REPAIR OF FRONT BONNET, FRONT BONNET HINGE, FRONT SUPPORT TOP PANEL, FRONT SUPPORT RH SIDE PANEL, FRONT SUPPORT RH SIDE BAR, FRONT RADIATOR TOP PANEL AND FRONT RH FENDER INNER BRACKET		\$1,400.00	\$550.00
			\$2,960.00	\$1,400.00
GRAND TOTAL			\$12,027.15	\$6,742.45
RECOMMENDED COST OF REPAIRS				\$6,742.45
Report Ref No: CS/TP24100210/Knh3m4				

KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.