

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS24100211/UNP3M4**Date:** 28/10/2024REFERENCE

Insured/Claimant: LAI MEE HAR Policy No: MPC23A00313802
Date of Loss: 25/09/2024 Nature of Claim: OD Claim No: DMPC2401282H/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNC5882G**
Make & Model: HONDA SHUTTLE, 1.5 G CVT SENSING (A) Engine No: L15B6051900
Reg. Date: 29/10/2021 (Man. Year: 2021) Chassis No: GK82201571
Colour: White Odometer: 31779 km
Engine Capacity: 1496 cc
Market Value/New Car Price: S\$93,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60R15 Rear Tyre Size: 185/60R15
Front Left Side: Dunlop 4 mm Rear Left Side: Ecopia 4 mm
Front Right Side: Dunlop 4 mm Rear Right Side: Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,015.00	3,740.00	3,275.00	46.69
Miscellaneous Items	400.00	185.00	215.00	53.75
Labour	2,250.00	1,170.00	1,080.00	48.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,665.00	5,095.00	4,570.00	47.28
Approved Total (Overridden) (S\$)		4,050.00		
- Excess (S\$)	0.00	1,000.00	-1,000.00	
(S\$)	9,665.00	3,050.00	6,615.00	68.44
+ GST 9.00/9.00% (S\$)	869.86	274.50	595.36	68.44
Nett Amount (S\$)	10,534.86	3,324.50	7,210.36	68.44

INSPECTION

Date of Assignment: 10/10/2024 Present Location: Jack Cars Enterprise Pte Ltd (HQ)
Date Inspected: 11/10/2024 Inspected At: JACK CARS ENTERPRISE PTE LTD (HQ)
Estimated Period of Repair: 5.0 days BLK 3007 UBI ROAD 1, #01 - 450
SINGAPORE 408700

Adjuster: MARCUS CHUA**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 28 Oct 2024)	
Parts:	N/A	HONDA SHUTTLE 1.5 G CVT SENSING (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNC5882G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (WCP)	Distorted	880.00 F	*880.00 F
2	1		*FRONT BUMPER UPPER GRILLE (WCP)	Cracked	410.00 F	*410.00 F
3	1		*FRONT BUMPER LOWER GRILLE (WCP)	Torn	380.00 F	*380.00 F
4	1		*FOG LAMP COVER - RIGHT FOG LAMP COVER - LEFT INSTEAD OF RIGHT (WCP)	Torn/Missing	170.00 F	*170.00 F
5	1		*FRONT REINFORCEMENT (WCP)	Dented	950.00 F	*950.00 F
6	1		*FRONT BUMPER BRACKET - LEFT & RIGHT (WCP)	Not Necessary	200.00 F	*- F
7	1		*HEADLIGHT - LEFT (WCP)	Serviceable	2,500.00 F	*- F
Supplementary #1						
8	1		*FRONT SUPPORT PANEL (WCP)	Dented/Bent	430.00 F	*430.00 F
9	1		*HEADLIGHT LOWER BRACKET - LEFT (WCP)	Cracked	180.00 F	*180.00 F

F=Franchise part.

Sub Total (S\$)	6,100.00	3,400.00
+ Margin on L,N Items 15.00/10.00% (S\$)	915.00	340.00
Total Parts (S\$)	7,015.00	3,740.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	"HONDA" EMBLEM Not Necessary	75.00	0.00
2	1	CLIPS , RIVETS & SCREWS Necessary	100.00	20.00
3	1	FRONT NUMBER PLATE & COVER Scratched	95.00	35.00
Supplementary #1				
4	1	AIRCON GAS	80.00	80.00
5	1	COOLANT Necessary	50.00	50.00
Sub Total (\$\$)			400.00	185.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PUTTY & SPRAY PAINT OF AFFECTED AREA	New	800.00	540.00
2	TO PANEL BEAT & TO REMOVE DAMAGED & NECESSARY PARTS & ATTACHEMENTS; KNOCK, JACK, WELD, RESHAPE AND ALIGN ALL AFFECTED PORTIONS.	New	1,200.00	600.00
3	TO CHECK LIGHTING SYSTEM ,WIRING & REWIRE	New	250.00	30.00
Gross Labour Cost (\$\$)			2,250.00	1,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >