



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SKZ 9827E

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER	DISTORTED	\$1,975.00	\$1,710.00
1	REAR BUMPER LOWER BRACKET	DEFORMED	\$92.00	\$92.00
1	REAR BUMPER LOWER DIFFUSER	DEFORMED	\$547.00	\$547.00
1	REAR BUMPER REINFORCEMENT	DENTED	\$499.00	\$499.00
4	REAR BUMPER REVERSE SENSOR 'O' RING L/R @\$25.00	NECESSARY (1PC ONLY)	\$100.00	\$25.00
4	REAR BUMPER REVERSE SENSOR HOLDER L/R @\$35.00	NECESSARY	\$140.00	\$140.00
4	REAR BUMPER REVERSE SENSOR L/R @\$212.00	DAMAGED (1PC ONLY)	\$848.00	\$212.00
1	REAR BUMPER RH REFLECTOR	CRACKED	\$187.00	\$187.00
2	REAR BUMPER SIDE L/R @\$398.00	O/S DEFORMED	\$796.00	\$398.00
2	REAR BUMPER SIDE RETAINER L/R @\$177.00	NOT NECESSARY	\$354.00	\$0.00
1	REAR BUMPER TOW HOOK COVER	NOT NECESSARY	\$70.00	\$0.00
1	REAR END PANEL	DENTED	\$1,035.00	\$890.00
1	REAR END PANEL ANTENNA SENSOR	CRACKED	\$170.00	\$170.00
1	REAR END PANEL INNER TOP GARNISH	DEFORMED	\$307.00	\$307.00
1	REAR EXHAUST GASKET	NOT NECESSARY	\$87.00	\$0.00
1	REAR EXHAUST RUBBER MOUNTING	NOT NECESSARY	\$95.00	\$0.00
1	REAR EXHAUST SILENCER BOX	NOT NECESSARY	\$1,775.00	\$0.00
1	REAR RH TAILLAMP	NOT NECESSARY	\$1,170.00	\$0.00
1	REAR TAILGATE	DENTED	\$2,895.00	\$2,895.00
1	REAR TAILGATE 'ECO0' EMBLEM	NECESSARY	\$147.00	\$147.00
1	REAR TAILGATE 'KADJAR' EMBLEM	NECESSARY	\$217.00	\$217.00
1	REAR TAILGATE 'LOGO' EMBLEM	NECESSARY	\$185.00	\$185.00
1	REAR TAILGATE 'RENAULT' EMBLEM	NECESSARY	\$166.00	\$166.00
1	REAR TAILGATE CAMERA	NOT NECESSARY	\$1,076.00	\$0.00
2	REAR TAILGATE DAMPER L/R @\$195.00	NOT NECESSARY	\$390.00	\$0.00
2	REAR TAILGATE HINGES L/R @\$137.00	NOT NECESSARY	\$274.00	\$0.00
1	REAR TAILGATE INNER LOWER GARNISH	CRACKED	\$187.00	\$187.00
2	REAR TAILGATE INNER RUBBER STOPPER L/R @\$45.00	NOT NECESSARY	\$90.00	\$0.00
1	REAR TAILGATE INNER TRIM BOARD	CRACKED	\$979.00	\$780.00
1	REAR TAILGATE MECHANISM LOCK	DAMAGED	\$373.00	\$373.00



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
2	REAR TAILGATE NUMBER PLATE LAMP L/R @\$154.00	O/S CRACKED	\$308.00	\$154.00
1	REAR TAILGATE OPENER SWITCH BOTTOM	NOT NECESSARY	\$195.00	\$0.00
2	REAR TAILGATE REFLECTOR L/R @\$517.00	NOT NECESSARY	\$1,034.00	\$0.00
1	REAR TAILGATE WEATHER STRIP	CUT	\$277.00	\$277.00
1	REAR TAILGATE WINDSCREEN MOULDING	NECESSARY	\$199.00	\$199.00
	<b>LESS 10.00% DISCOUNT</b>		(\$1,923.90)	(\$1,075.70)
			\$17,315.10	\$9,681.30

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	\$50.00	\$30.00
1	REAR BUMPER NUMBER PLATE (SN)	NOT NECESSARY	\$25.00	\$0.00
1	REAR BUMPER NUMBER PLATE FRAME (SN)	NOT NECESSARY	\$50.00	\$0.00
1	SET REAR END PANEL INNER TOP GARNISH CLIPS (SN)	NECESSARY	\$30.00	\$10.00
1	SET REAR TAILGATE INNER TRIM BOARD CLIPS (SN)	NECESSARY	\$50.00	\$30.00
1	REAR TAILGATE LOWER CHROME MOULDING (SN)	DEFORMED	\$250.00	\$100.00
1	REAR TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	\$80.00	\$60.00
			\$535.00	\$230.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND REWIRE FOR PARKING SENSOR		\$80.00	\$80.00
	TO REMOVE, REINSTALL TAILGATE WINDSCREEN		\$150.00	\$120.00
	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR)		\$80.00	\$60.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT		\$1,000.00	\$500.00
	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE, RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT	NOT NECESSARY	\$100.00	\$0.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT		\$1,000.00	\$600.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL		\$80.00	\$60.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE, REINSTALL TAILGATE MECHANISM AND CHECK FOR FUNCTION		\$80.00	\$60.00
			\$2,570.00	\$1,480.00
GRAND TOTAL			\$20,420.10	\$11,391.30
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$9,100.00
Report Ref No: CS/AGI24060211/Aqh3m4				

**LWP**

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.