

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internationa	le Des Experts En	Automobile
MS	AUTO & GENERAL	INSURANCE (S) PL	Ref:	CS/AGI24060211/Aqh3m4
	(BUDGET DIRECT I 190 CLEMENCEAU	NSURANCE)	Date:	27/08/2024
		PING CENTRE SINGAPORE 239924	Code:	AGI
1.		Policy Particulars :- T	HIRD PARTY CLAI	M
	Insured Veh.	SMF 3617R	Veh. Inspected	SKZ 9827E
	Policy No.	-	Coverage	0
	Claim No.	C10030095/CH	Excess	\$0.00
	Assign From	MICHAEL	Assign Date	24/06/2024
2. Vehicle Details				
	Make & Model	RENAULT KADJAR	C.C	1461
	Engine No.	K9KF647D014435	Year of Reg.	18/02/2016
	Chassis No.	VF1RFE00654465058	Colour	SILVER
	Odometer	200161 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: SPORTS RIM		
3. Conditions of Tyres				
		Size	Make	Balance (mm)
	R/H Front Tyre	225/45R19	GRENLANDER	6
			GRENLANDER	6
	L/H Front Tyre	225/45R19	ORIEND WIDER	•
	L/H Front Tyre R/H Rear Tyre	225/45R19 225/45R19	GRENLANDER	6
4.	R/H Rear Tyre	225/45R19	GRENLANDER GRENLANDER	6
	R/H Rear Tyre L/H Rear Tyre	225/45R19 225/45R19	GRENLANDER GRENLANDER of Damages	6
THE	R/H Rear Tyre L/H Rear Tyre	225/45R19 225/45R19 Description of the Damages at the Rear Portion of the Damages at	GRENLANDER GRENLANDER of Damages	6
THE	R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAIN	225/45R19 225/45R19 Description of the Damages at the Rear Portion of the Damages at	GRENLANDER GRENLANDER of Damages N.	6
THE	R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAIN	225/45R19 225/45R19 Description of the Description of the DAMAGES AT THE REAR PORTIONS.	GRENLANDER GRENLANDER of Damages N.	6
THE	R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAINI 1AGES SEE DETAILS	225/45R19 225/45R19 Description of the properties of the properti	GRENLANDER GRENLANDER of Damages N. formation	6 6
THE	R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAIN AGES SEE DETAILS Accident Date	225/45R19 225/45R19 Description of ED DAMAGES AT THE REAR PORTION General Interpretation of Education (Control of Education (Contr	GRENLANDER GRENLANDER of Damages N. formation	6 6
THE	R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAIN AGES SEE DETAILS Accident Date	225/45R19 225/45R19 Description of the properties of the propert	GRENLANDER GRENLANDER of Damages N. formation Inspection Date	6 6
THE DAM 5.	R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAINI AGES SEE DETAILS Accident Date Survey held at	225/45R19 225/45R19 Description of ED DAMAGES AT THE REAR PORTIONS. General Info 21/06/2024 TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921 Rema	GRENLANDER GRENLANDER of Damages N. formation Inspection Date	6 6
THE DAM 5. 5a. A) TI	R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAINI AGES SEE DETAILS Accident Date Survey held at	225/45R19 225/45R19 Description of the properties of the propert	GRENLANDER GRENLANDER of Damages N. formation Inspection Date	25/06/2024

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days