

ASSIGNMENT

Front: _____ Date: _____

Estim: _____

OD / TP / TP RES / CD RES / EVA / INV / MV

To in Vehicle No: _____

at Work / Shop / Home / Other

of _____

Insured: _____

Policy No: _____

Claimed: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vehicle: _____

(Policy Condition)

Remark: The vehicle had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repair: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBE8737E - Yr Regn: 2016/Apr

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Hince C.D. 2982

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 274793 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KDH2010189568

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195R15C

R: 195R15C

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 26 mm

R/Bal. 26 mm

L/Bal. 26 mm

L/Bal. 06 mm

D.O.A.

D.O.I. 14/10/24

Survey held at NSI

Des. of Damages: Frt / Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>7P111</u>
	<u>COE Expiry</u>
	<u>Estimate given during : Yes (✓)</u>
	<u>1st Survey : No ()</u>
	<u>MV : 80K</u>
	<u>PV : 6.2K</u>
	<u>Nett : 23.8K</u>
	<u>867E</u>

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Inve (\$ _____)

Survey Fee: _____

Transportation: _____

3 + RS. \$ _____

Photos

Others

Report Format: _____

Report Form: _____

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

EMBRACE FUNERAL SERVICES PTE LTD
 624B PUNGGOL CENTRAL #13-310 PUNGGOL
 SPECTRA
 SINGAPORE 822624

Contact : 96921100 83395163

TAX INVOICE

Repair Code : CLM18409

Date in : 14/10/2024

Vehicle Num. : GBE8737E

Model : TOYOTA HIACE 3.0 A

Chassis/Eng# : KDH2010189568/1KD2589507

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>at</i>	1	836.70	✓ 836.70
FRONT BUMPER RH SIDE RETAINER <i>new</i>	1	154.80	+ 154.80
FRONT CORNER PANEL <i>Rego</i>	1	290.50	+ 290.50
FRONT RH DOOR <i>Debit</i>	1	2904.10	✓ 2,904.10
FRONT RH DOOR CHECKER	1	96.50	+ 96.50
FRONT RH DOOR HINGE (LOWER) <i>new</i>	1	199.40	+ 199.40
FRONT RH DOOR HINGE (TOP)	1	199.40	+ 199.40
FRONT RH DOOR SIDE MIRROR ASSY <i>new</i>	1	1507.50	1,507.50
FRONT RH DOOR WEATHER STRIP <i>new</i>	1	249.40	+ 249.40
FRONT RH HEADLAMP <i>at</i>	1	1264.90	✓ 1,264.90
Subtotal before discount			7,703.20
Percentage discount 25%			1,925.80
Sub-total 1			5,777.40
FRONT BUMPER CLIPS - SET <i>new</i>	1	50.00	30 50.00
FRONT RH DOOR 3D ART WORK STICKER <i>new</i>	1	450.00	200 450.00
FRONT RH DOOR COMPANY DETAIL STICKER <i>new</i>	1	25.00	✓ 25.00
FRONT RH DOOR INNER TRIM BOARD CLIPS - SET <i>new</i>	1	50.00	+ 50.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

EMBRACE FUNERAL SERVICES PTE LTD
624B PUNGGOL CENTRAL #13-310 PUNGGOL
SPECTRA
SINGAPORE 822624

Contact : 96921100 83395163

TAX INVOICE

Repair Code : CLM18409
Date in : 14/10/2024
Vehicle Num. : GBE8737E
Model : TOYOTA HIACE 3.0 A
Chassis/Eng# : KDH2010189568/1KD2589507

Subtotal before discount	575.00
Percentage discount 0%	0.00
Sub-total 2	575.00
Parts-total	6,352.40

LABOUR

- To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)
- To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.
- To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.
- To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.
- To apply anti-rust chemical on repaired and replaced panel.

30 80.00
60 120.00
400 1,000.00
500 900.00
30 80.00

Labour Total 2,180.00
Parts & Labour Total 8,532.40

*** This is a computer-generated document which requires no signature.***

page 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Admin L
L/S 14/10/24.
04 days