

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24100227/AUA3Q2**Date:** 19/05/2025**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220140530
Claimant Vehicle No :	ES6628R	Insured Vehicle No :	SCY6308G
Date of Loss:	08/10/2024	Nature of Claim:	TP
		Claim No:	9687560530SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	ES6628R	Engine No:	27492030237809
Make & Model:	MERCEDES-BENZ E200, 2.0 SEDAN (R17) (A)	Chassis No:	WDD2120342B061858
Reg. Date:	23/12/2014 (Man. Year: 2014)	Odometer:	114498 km
Colour:	White		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R17	Rear Tyre Size:	245/45 R17
Front Left Side:	KAPSEN 6 mm	Rear Left Side:	KAPSEN 6 mm
Front Right Side:	KAPSEN 6 mm	Rear Right Side:	KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,169.42	9,031.02	9,138.40	50.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,150.00	1,430.00	2,720.00	65.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,319.42	10,461.02	11,858.40	53.13
Approved Total (Overridden) (S\$)		7,500.00		
(S\$)	22,319.42	7,500.00	14,819.42	66.40
+ GST 9.00/9.00% (S\$)	2,008.75	675.00	1,333.75	66.40
Nett Amount (S\$)	24,328.17	8,175.00	16,153.17	66.40
+ Car Rental (6.0 x S\$120.00/day) (S\$)		720.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		8,897.18		
Global Sum Settlement (S\$)		8,850.00		

INSPECTION

Date of Assignment:	10/10/2024		
Date Inspected:	10/10/2024	Inspected At:	Xin Hua Workshop Pte Ltd (HQ) 23 Kaki Bukit Ave 4 #04-01 Singapore 415933
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING**Manager:** NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,645.20 FL	*1,645.20 FL
2	1		*FRONT FOGLAMP COVER WITH CHROME RH	Not Necessary	225.30 FL	*- FL
3	1		*FRONT BUMPER SENSOR (3 PCS)	Damaged (2 PCS ONLY)	1,035.60 FL	*690.40 FL
4	3		*FRONT BUMPER SENSOR HOLDERS	Necessary	137.40 FL	*137.40 FL
5	1		*FRONT BUMPER SENSOR WIREHARNESS	Not Necessary	1,452.30 FL	*- FL
6	1		*FRONT BUMPER SIDE RETAINER RH	Not Necessary	125.60 FL	*- FL
7	1		*FRONT BUMPER BRACKET RH	Not Necessary	123.20 FL	*- FL
8	1		*FRONT BUMPER SIDE LOCK BRACKET RH	Not Necessary	108.50 FL	*- FL
9	1		*BONNET	Dented	2,458.90 FL	*2,458.90 FL
10	1		*BONNET LOCK	Not Necessary	568.30 FL	*- FL
11	1		*BONNET LOGO	Not Necessary	125.80 FL	*- FL
12	2		*BONNET HINGE	Not Necessary	292.00 FL	*- FL
13	1		*FRONT GRILLE	Not Necessary	875.30 FL	*- FL
14	1		*FRONT SUPPORT PANEL	Not Necessary	987.50 FL	*- FL
15	1		*HEAD LAMP RH	Smashed	4,987.50 FL	*3,810.00 FL
16	1		*HEAD LAMP PANEL RH	Not Necessary	425.30 FL	*- FL
17	1		*FRONT FENDER RH	Buckled	1,040.00 FL	*1,040.00 FL
18	1		*FRONT FENDER COWLING (FRONT) RH	Deformed	185.90 FL	*185.90 FL
19	1		*FRONT FENDER COWLING (REAR) RH	Not Necessary	170.00 FL	*- FL
20	1		*FRONT FENDER INNER GARNISH RH	Not Necessary	225.30 FL	*- FL
21	1		*SIDE SKIRT RH	Not Necessary	925.30 FL	*- FL
22	1		*FRONT RIM RH	Not Necessary	1,245.82 FL	*- FL
23	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
24	1		*SET FRONT FENDER COWLING CLIP	Necessary	30.00 FS	*30.00 FS
25	1		*SET FRONT FENDER INNER GARNISH CLIP RH	Not Necessary	30.00 FS	*- FS
26	1		*SIDE SKIRT CLIP SET RH	Not Necessary	30.00 FS	*- FS
27	1		*FRONT WHEEL TYRE RH	Not Necessary	600.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	20,106.02	10,027.80
- List Item Discount on L Items 10.00/10.00% (\$)	1,936.60	996.78
Total Parts (\$)	18,169.42	9,031.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING REMOVAL AND REPLACING PARTS	New	1,600.00	600.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	600.00
3	TUFF COAT	New	250.00	0.00
4	WIRING CHECK	New	150.00	30.00
5	FOUR WHEEL ALIGNMENT	New	150.00	0.00
6	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	400.00	200.00
Gross Labour Cost (\$\$)			4,150.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >