

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24100229/AUA3Q2**Date:** 19/02/2025**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800113065
Claimant Vehicle No :	GBJ367R	Insured Vehicle No :	SME1837R
Date of Loss:	10/10/2024	Nature of Claim:	TP
		Claim No:	9829173476SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ367R	Engine No:	HR16134814D
Make & Model:	NISSAN NV200, 1.6 DX-2 (A)	Chassis No:	VM20128977
Reg. Date:	10/12/2018 (Man. Year: 2018)	Odometer:	92998 km
Colour:	Black		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	Grenlander 6 mm	Rear Left Side:	Grenlander 6 mm
Front Right Side:	Grenlander 6 mm	Rear Right Side:	Grenlander 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,754.85	6,487.54	9,267.31	58.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,340.00	2,520.00	2,820.00	52.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,094.85	9,007.54	12,087.31	57.30
Approved Total (Overridden) (S\$)		7,200.00		
(S\$)	21,094.85	7,200.00	13,894.85	65.87
+ GST 9.00/9.00% (S\$)	1,898.54	648.00	1,250.54	65.87
Nett Amount (S\$)	22,993.39	7,848.00	15,145.39	65.87
+ Loss of Use (11.0 x S\$80.00/day) (S\$)		880.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		8,755.25		
Global Sum Settlement (S\$)		8,750.00		

INSPECTION

Date of Assignment:	11/10/2024	
Date Inspected:	11/10/2024	Inspected At: HD Perfect Autowork Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	9.0 days	

Adjuster: ADRIAN LING**Manager:** NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	566.90 FL	*566.90 FL
2	1		*REAR BUMPER SPONGE	Cracked	145.89 FL	*145.89 FL
3	1		*REAR BUMPER SIDE RETAINER	O/S Cracked	79.40 FL	*39.70 FL
4	1		*TAILGATE	Dented	2,080.40 FL	*2,080.40 FL
5	2		*TAILGATE STOPPER	Not Necessary	42.80 FL	*- FL
6	1		*TAILGATE LOGO	Necessary	67.50 FL	*67.50 FL
7	1		*TAILGATE NV200 EMBLEM	Necessary	66.30 FL	*66.30 FL
8	1		*TAILGATE VENETTE EMBLEM	Necessary	68.50 FL	*68.50 FL
9	1		*TAILGATE CHINESE WORDS STICKER	Necessary	110.40 FL	*30.00 FL
10	1		*TAILGATE OUTER MOULDING	Not Necessary	389.50 FL	*- FL
11	1		*TAILGATE LOWER LOCK CENTER COVER GARNISH	Not Necessary	235.50 FL	*- FL
12	1		*TAILGATE INNER LOCK	Not Necessary	271.40 FL	*- FL
13	1		*TAILGATE LOWER LOCK	Not Necessary	26.40 FL	*- FL
14	1		*TAILGATE INNER TRIM	Not Necessary	368.70 FL	*- FL
15	1		*TAILGATE WEATHERSTRIP	Cut	316.80 FL	*316.80 FL
16	1		*TAIL LAMP RH	Smashed	294.60 FL	*294.60 FL
17	1		*TAIL LAMP PANEL RH	Dented	434.70 FL	*434.70 FL
18	1		*TAIL LAMP INNER PANEL RH	Repair	582.30 FL	*- FL
19	1		*REAR SIDE PANEL RH	Buckled	1,540.20 FL	*1,540.20 FL
20	1		*REAR SIDE INNER PANEL RH	Repair	1,769.40 FL	*- FL
21	1		*REAR SIDE INNER PANEL AIR VENT RH	Deformed	169.40 FL	*169.40 FL
22	1		*REAR INNER CORNER PANEL (LOWER) RH	Repair	476.40 FL	*- FL
23	1		*REAR END PANEL (OUTER)	Dented	598.60 FL	*598.60 FL
24	1		*REAR END PANEL (INNER)	Repair	1,489.50 FL	*- FL
25	1		*REAR FLOOR PANEL MAT	Not Necessary	1,219.80 FL	*- FL
26	1		*REAR FLOOR CORNER EXTEND PANEL RH	Not Necessary	294.10 FL	*- FL
27	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
28	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
29	1		*SET TAIL LAMP CLIP	Not Necessary	30.00 FS	*- FS
30	2		*TAIL LAMP PANEL SEALANT	Not Necessary	120.00 FS	*- FS
31	1		*TAILGATE STICKER 70KM/H	Necessary	40.00 FS	*15.00 FS
32	1		*TAILGATE STICKER 6 PAX	Necessary	40.00 FS	*15.00 FS
33	1		*SET TAILGATE INNER TRIM CLIP	Not Necessary	50.00 FS	*- FS
34	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
35	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	60.00 FS	*30.00 FS
36	1		*REAR SIDE INNER PANEL SEALANT	Not Necessary	300.00 FS	*- FS
37	1		*REAR INNER SIDE PANEL SEALANT	Necessary	300.00 FS	*60.00 FS
38	2		*REAR SIDE GLASS SEALANT	Necessary	160.00 FS	*30.00 FS
39	2		*REAR SIDE GLASS INNER SEAL	Necessary	120.00 FS	*30.00 FS
40	1		*REAR END PANEL (OUTER) SEALANT	Necessary	150.00 FS	*60.00 FS
41	1		*REAR END PANEL (INNER) SEALANT	Not Necessary	150.00 FS	*- FS
42	1		*REAR FLOOR PANEL TOP BOARD (SPECAIL TYPE)	Cracked	1,500.00 FS	*400.00 FS
43	1		*SET REVERSE SENSOR	Not Necessary	220.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	17,125.39	7,129.49
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,370.54	641.95
Total Parts (\$\$)	15,754.85	6,487.54

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING AND REPLACE PARTS	New	2,000.00	1,200.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,800.00	1,000.00
3	WIRING BULB CHECKING	New	180.00	30.00
4	TRANSFER TAILGATE MECHANISM	New	80.00	60.00
5	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
6	REAR CHASSIS ALIGNMENT	New	250.00	0.00
7	REMOVE AND REFIX REAR REVERSE SENSOR	New	80.00	50.00
8	REMOVE AND REFIX SIDE PANEL GLASS	New	120.00	60.00
9	REMOVE AND REFIX REAR WINDSCREEN	New	120.00	120.00
10	REMOVE AND REFIX SLIDING DOOR FACILITATE FENDER REPLACEMENT	New	80.00	0.00
11	REMOVE AND REFIX SIDE PANEL RAILWAY	New	80.00	0.00
12	REMOVE AND REFIX REAR FLOOR PANEL TOP BOARD	New	250.00	0.00
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			5,340.00	2,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >