

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24100230/APA3Q2**Date:** 14/01/2025REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7220015329
Claimant Vehicle No : SMN8280C **Insured Vehicle No :** SDE6388T
 Date of Loss: 10/10/2024 Nature of Claim: TP Claim No: 0588803423SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMN8280C**
 Make & Model: TOYOTA C-HR HYBRID, 1.8 S CVT (A) Engine No: 2ZR2B72903
 Reg. Date: 24/05/2019 (Man. Year: 2018) Chassis No: ZYX102147090
 Colour: Blue Odometer: 375436 km
 Engine Capacity: 1797 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50R18 Rear Tyre Size: 225/50R18
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,101.32	4,130.30	2,971.02	41.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,350.00	930.00	2,420.00	72.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,451.32	5,060.30	5,391.02	51.58
Approved Total (Overridden) (S\$)		4,000.00		
Nett Amount (S\$)	10,451.32	4,000.00	6,451.32	61.73
+ Loss of Use (4.0 x S\$80.00/day) (S\$)		320.00		
(S\$)		4,320.00		
Liabe Amount (50.00%) (S\$)		2,160.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		2,162.18		
Global Sum Settlement (S\$)		2,150.00		

INSPECTION

Date of Assignment: 11/10/2024
 Date Inspected: 11/10/2024 Inspected At: YSK Auto Workshop (HQ)
 1 Kaki Bukit Avenue 6 @ AutoBay, #01-71
 Singapore 417883
 Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	790.80 FL	*790.80 FL
2	1		*FRONT BUMPER SIDE HOLDER	Not Necessary	85.90 FL	*- FL
3	1		*FRONT BUMPER LOWER	Not Necessary	369.40 FL	*- FL
4	1		*FRONT BUMPER LOWER SIDE GARNISH	Cut	82.30 FL	*82.30 FL
5	1		*FRONT BUMPER SIDE GRILLE	Not Necessary	92.40 FL	*- FL
6	1		*FRONT BUMPER INNER SIDE BRACKET	Not Necessary	79.90 FL	*- FL
7	1		*HEADLAMP	Cut	2,978.30 FL	*2,978.30 FL
8	1		*FRONT FENDER	Dented	749.60 FL	*749.60 FL
9	1		*FRONT FENDER INNERSHIELD	Not Necessary	236.40 FL	*- FL
10	1		*FRONT FENDER ARC GARNISH	Deformed	199.40 FL	*199.40 FL
11	1		*FRONT FENDER INNER ENCLOSURE	Not Necessary	35.90 FL	*- FL
12	1		*FRONT FENDER QUARTER GARNISH	Not Necessary	83.50 FL	*- FL
13	1		*FRONT FENDER HYBRID EMBLEM	Not Necessary	87.40 FL	*- FL
14	1		*FRONT LOWER ARM	Not Necessary	497.90 FL	*- FL
15	1		*FRONT SHOCK ABSORBER	Not Necessary	485.40 FL	*- FL
16	1		*FRONT KNUCKLE ARM	Not Necessary	519.30 FL	*- FL
17	1		*FRONT WHEEL HUB C/W BEARING	Not Necessary	367.70 FL	*- FL
18	1		*FRONT ANTI ROLL BAR LINKAGE	Not Necessary	113.60 FL	*- FL
19	1		*FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
20	1		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	30.00 FS	*- FS
21	1		*FRONT FENDER WHEEL ARC GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
22	1		*FRONT WHEEL RIM	Cut	850.00 FS	*480.00 FS
23	1		*FRONT TYRE	Not Necessary	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,065.10	5,330.40
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,963.78	1,200.10
Total Parts (\$\$)	7,101.32	4,130.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING.	New	1,200.00	500.00
2	SPRAY PAINTING.	New	1,000.00	400.00
3	WIRING.	New	100.00	30.00
4	TO APPLY TUFF COAT.	New	200.00	0.00
5	TO REMOVE FRONT UNDERCARRIAGE.	New	350.00	0.00
6	TO REMOVE STEERING RACK & PINION.	New	200.00	0.00
7	TO PERFORM WHEEL ALIGNMENT.	New	300.00	0.00
Gross Labour Cost (\$\$)			3,350.00	930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >