

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24100232/EVP3E2**Date:** 30/05/2025REFERENCE

Handling Insurer: ECICS Limited Policy No:

Claimant Vehicle No : SGR3828G **Insured Vehicle No :** SMF3550Z

Date of Loss: 12/10/2024 Nature of Claim: TP Claim No: DMPC2401381H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGR3828G**

Make & Model: TOYOTA WISH, 1.8 (A) Engine No: 2ZR1832142

Reg. Date: 09/09/2016 (Man. Year: 2016) Chassis No: JTDGG20W70J005149

Colour: Silver Odometer: 156921 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R16 Rear Tyre Size: 195/60 R16

Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,475.98	4,511.43	1,964.55	30.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,811.52	4,187.52	1,624.00	27.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,287.50	8,698.95	3,588.55	29.20
+ GST 9.00/9.00% (S\$)	1,105.88	782.91	322.97	29.20
Nett Amount (S\$)	13,393.38	9,481.86	3,911.52	29.20

INSPECTION

Date of Assignment: 14/10/2024

Date Inspected: 13/05/2025 Inspected At: Borneo Motors (S) Pte Ltd (Pandan)
2 Pandan Crescent
Singapore 128462

Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 May 2025)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGR3828G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY	Necessary	100.00 FS	*50.00 FS
2	1		*SEALANT	Necessary	120.00 FS	*100.00 FS
3	1		*SOLAR FILM FOR REAR WINDSCREEN	Necessary	480.00 FS	*480.00 FS
4	1		*PLATE, RR BUMPER	Dented	911.60 FL	*911.60 FL
5	2		*PAD, RR BUMPER, RH	Necessary	15.00 FL	*15.00 FL
6	2		*PAD, RR BUMPER, RH	Necessary	15.00 FL	*15.00 FL
7	8		*PIECE, RR BUMPER	Necessary	46.40 FL	*46.40 FL
8	1		*RETAINER, RR BUMPER	Not Necessary	70.20 FL	*- FL
9	1		*SUPPORT, RR BUMPER	Not Necessary	149.10 FL	*- FL
10	1		*RETAINER, RR BUMPER	Not Necessary	70.20 FL	*- FL
11	1		*SUPPORT, RR BUMPER	Not Necessary	149.10 FL	*- FL
12	1		*PANEL SUB-ASSY, BODY	Not Necessary	817.70 FL	*- FL
13	1		*PLATE, BACK DOOR	Not Necessary	413.40 FL	*- FL
14	1		*PANEL SUB-ASSY, BACK	Dented	2,263.80 FL	*2,263.80 FL
15	1		*WEATHERSTRIP, BACK	Not Necessary	465.30 FL	*- FL
16	1		*GLASS SUB-ASSY, BACK	Necessary	1,480.50 FL	*1,480.50 FL
17	1		*LOCK ASSY, BACK DOOR	Not Necessary	571.50 FL	*- FL
18	1		*EMBLEM, SYMBOL	Necessary	73.50 FL	*73.50 FL
19	1		*PLATE, LUGGAGE COMPT	Necessary	56.90 FL	*56.90 FL
20	1		*ANTENNA, ELECTRICAL	Broken	266.20 FL	*266.20 FL
21	2		*SIKA 182010 SIKA TACK GO! (BLA	Necessary	216.00 FL	*216.00 FL
22	1		*SIKA 207. G+P ADHESIVE PRIMER	Necessary	200.00 FL	*200.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,951.40	6,174.90
- List Item Discount on L Items 30.00/30.00% (\$\$)	2,475.42	1,663.47
Total Parts (\$\$)	6,475.98	4,511.43

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE AND REPAIR ACCIDENT DAMAGED PARTS	New	2,880.00	1,728.00
2	TO RESPRAY ALL ACCIDENT AFFECTED AREAS	New	1,888.00	1,416.00
3	TO CHECK WIRING SYSTEM	New	97.92	97.92
4	TO DRILL HOLE AND INSTALL REVERSE SENSOR	New	144.00	144.00
5	TO REMOVE AND TRANSFER BOOT COMPONENT TO NEW BOOT	New	288.00	288.00
6	TO RESET ECU AND REPROGRAMME	New	144.00	144.00
7	TO REMOVE AND INSTALL REAR WINDSCREEN	New	369.60	369.60
Gross Labour Cost (S\$)			5,811.52	4,187.52

Report was unsubmitted during this print-out.

< END OF ESTIMATES >