



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO FBE 5763Z

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
2	FRONT FORK TUBE ASSY	BENT/TWISTED	\$640.00	\$640.00
1	FORK UNDER BRACKET	BENT	\$225.00	\$180.00
1	FRONT WHEEL RIM	BENT/WARPED	\$480.00	\$300.00
1	FRONT RIM SHAFT	SERVICEABLE	\$105.00	\$0.00
1	FRONT RIM BEARING	NECESSARY	\$98.00	\$60.00
1	FRONT BRAKE DISC	NOT NECESSARY	\$265.00	\$0.00
1	HANDLE-BAR	BENT	\$245.00	\$165.00
1	HANDLE BAR INNER BRACKET	BENT	\$188.00	\$115.00
1	SET HANDLE-BAR END	NOT FITTED	\$120.00	\$0.00
1	SET HAND GRIP	TORN/CUT	\$95.00	\$95.00
1	HEADLAMP	CRACKED	\$380.00	\$380.00
1	SET SIDE MIRROR	CUT	\$140.00	\$68.00
1	FRONT SIGNALS	CRACKED	\$190.00	\$115.00
1	BRAKE LEVER	SERVICEABLE	\$125.00	\$0.00
1	SET FAIRING ASSY	CRACKED	\$650.00	\$480.00
1	FRONT FOOTREST BRACKET	BENT	\$185.00	\$145.00
2	FRONT FOOTREST RUBBERS	TORN	\$90.00	\$60.00
1	BRAKE PEDAL	CUT	\$145.00	\$145.00
1	EXHAUST ASSY	TO REPAIR SEE LABOUR	\$1,800.00	\$0.00
1	BASKET	TO REPAIR SEE LABOUR	\$115.00	\$0.00
2	REAR FOOTRESTS	SERVICEABLE	\$180.00	\$0.00
2	REAR FOOTREST BRACKETS	SERVICEABLE	\$320.00	\$0.00
	<b>LESS 10.00% DISCOUNT</b>		(\$678.10)	(\$294.80)
			\$6,102.90	\$2,653.20

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET NUMBER PLATE (SN)	NOT NECESSARY	\$38.00	\$0.00
2	FORK OILS (SN)	NOT NECESSARY	\$30.00	\$0.00
2	FORK OIL SEALS (SN)	NOT NECESSARY	\$56.00	\$0.00
1	SET STEERING CONE (SN)	NECESSARY	\$150.00	\$80.00



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BOX (SN)	CUT	\$480.00	\$280.00
1	REAR BOX BRACKET (SN)	TO REPAIR SEE LABOUR	\$180.00	\$0.00
1	STICKER (SN)	NECESSARY	\$120.00	\$80.00
			\$1,054.00	\$440.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	NOT NECESSARY	\$80.00	\$0.00
	TO REPAIR BODY FRAME	NOT NECESSARY	\$480.00	\$0.00
	TO PROVIDE LABOUR. INCLUSIVE OF THE REPAIR OF EXHAUST ASSY, BASKET AND REAR BOX BRACKET		\$420.00	\$300.00
			\$980.00	\$300.00
<b>GRAND TOTAL</b>			<b>\$8,136.90</b>	<b>\$3,393.20</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>			<b>\$2,700.00</b>
Report Ref No: CS/INC24100233/Unh3e2				

TOTAL FOR SPARE PARTS: \$ 7,156.90 \$ 3,093.20  
TOTAL FOR LABOUR : \$ 980.00 \$ 300.00  
TOTAL REPAIR COST: \$ 8,136.90 \$ 3,393.20

**CKS**

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.