

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunus Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS24060213/RQP3M4**Date:** 13/08/2024REFERENCE

Insured/Claimant: MENG FANWEI Policy No: MPC24A0C121800
Date of Loss: 21/06/2024 Nature of Claim: OD Claim No: DMPC2400770H/AF

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNP5916A**
Make & Model: TOYOTA LEXUS, 2.0 RX300 5DR SUV (AT) (4WD) LUXURY (A) Engine No: 8ARW806747
Reg. Date: 27/04/2018 (Man. Year: 2018) Chassis No: JTJBAMCA302050619
Colour: Black Odometer: 92640 km
Engine Capacity: 1998 cc
Market Value/New Car Price: S\$132,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55R20 Rear Tyre Size: 235/55R20
Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	31,856.86	20,762.00	11,094.86	34.83
Miscellaneous Items	0.00	0.00	0.00	
Total Labour	10,408.80	6,601.20	3,807.60	36.58
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	42,265.66	27,363.20	14,902.46	35.26
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	42,265.66	26,863.20	15,402.46	36.44
+ GST 9.00/9.00% (S\$)	3,803.91	2,417.69	1,386.22	36.44
Nett Amount (S\$)	46,069.57	29,280.89	16,788.68	36.44

INSPECTION

Date of Assignment: 24/06/2024 Present Location: Borneo Motors (S) Pte Ltd (Pandan)
Date Inspected: 24/06/2024 Inspected At: BORNEO MOTORS (S) PTE LTD
2 PANDAN CRESCENT
SINGAPORE 128462
Estimated Period of Repair: 7.0 days

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Aug 2024)
Parts:	143	TOYOTA LEXUS 2.0 RX300 5DR SUV (AT) (4WD) LUXURY (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNP5916A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	L52119-4D938	*COVER FR BUMPER	Torn	1,746.60 FL	*1,746.60 FL
2	2	L89348-48010	*RETAINER ULTRASONIC	Necessary	53.80 FL	*53.80 FL
3	1	L52127-48140	*COVER FR BUMPER	Not Necessary	66.90 FL	*- FL
4	1	L52128-48110	*COVER FR BUMPER	Not Necessary	66.90 FL	*- FL
5	1	L53142-48040	*GARNISH RADIATOR	Scratched	105.20 FL	*105.20 FL
6	1	L81482-48200	*COVER FOG LAMP LH	Scratched	172.60 FL	*172.60 FL
7	1	L53286-48020	*COVER FR BUMPER ARM	Not Necessary	111.90 FL	*- FL
8	1	L52126-48091	*BRACKET FOG LAMP	Not Necessary	223.70 FL	*- FL
9	2	L53384-22070	*CUSHION HOOD CTR	Not Necessary	23.00 FL	*- FL
10	1	L52535-48050	*RETAINER FR BUMPER	Bent	191.70 FL	*191.70 FL
11	1	L52536-48040	*RETAINER FR BUMPER	Not Necessary	191.70 FL	*- FL
12	1	L52438-48020	*COVER FR BUMPER	Scratched	187.40 FL	*187.40 FL
13	2	L75392-35220	*RETAINER OUTSIDE	Necessary	11.20 FL	*11.20 FL
14	1	L52411-48030	*GUARD FR BUMPER	Not Necessary	223.70 FL	*- FL
15	1	L52618-48021	*ABSORBER FR BUMPER	Not Necessary	256.60 FL	*- FL
16	2	T90467-07215	*CLIP	Not Necessary	7.20 FL	*- FL
17	1	L52611-48181	*ABSORBER FR BUMPER	Not Necessary	155.70 FL	*- FL
18	1	L52021-48051	*REINFORCEMENT	Not Necessary	1,142.30 FL	*- FL
19	1	L53395-48080	*SEAL HOOD TO	Necessary	71.10 FL	*71.10 FL
20	1	L53111-48330	*GRILLE RADIATOR	Not Necessary	1,862.00 FL	*- FL
21	1	L53112-48320	*GRILLE RADIATOR	Not Necessary	458.40 FL	*- FL
22	1	L53121-48130	*MOULDING RADIATOR	Cracked	824.70 FL	*824.70 FL
23	1	L53122-48050	*MOULDING RADIATOR	Not Necessary	1,347.40 FL	*- FL
24	1	L53301-48180	*HOOD SUB-ASSY	Bent	4,260.70 FL	*4,260.70 FL
25	2	T90950-06096	*TAPE SEAL	Necessary	12.40 FL	*12.40 FL
26	1	L53381-48100	*SEAL HOOD TO	Not Necessary	102.30 FL	*- FL
27	1	L53802-48140	*FENDER SUB-ASSY FR	Bent	2,304.00 FL	*2,304.00 FL
28	1	L53808-48060	*REINFORCEMENT	Not Necessary	237.10 FL	*- FL
29	2	L53384-22070	*CUSHION HOOD CTR	Not Necessary	23.00 FL	*- FL
30	1	L53883-48050	*SEAL FR FENDER LH	Necessary	149.20 FL	*149.20 FL
31	3	T53857-47011	*RETAINER FR WHEEL	Necessary	9.30 FL	*9.30 FL
32	1	L53154-48030	*GUIDE FR SIDE AIR	Necessary	123.30 FL	*123.30 FL
33	1	L53748-48020	*PLATE AIR SEALED	Necessary	84.30 FL	*84.30 FL
34	1	L53806-48190	*SHIELD SUB-ASSY	Deformed	767.60 FL	*767.60 FL
35	1	L75602-48050	*MOULDING SUB-ASSY	Deformed	313.50 FL	*313.50 FL
36	1	L81185-48D30	*UNIT HEADLAMP	Broken	13,364.40 FL	*13,364.40 FL
37	1	L81056-48C80	*COMPUTER SUB-ASSY	Not Necessary	1,879.80 FL	*- FL
38	1	L81220-48051	*LAMP ASSY FOG LH	Not Necessary	516.00 FL	*- FL
39	2	L89341-48040 C3	*SENSOR ULTRASONIC	Not Necessary	1,007.80 FL	*- FL
40	2	L89341-48040 J0	*SENSOR ULTRASONIC	Not Necessary	1,260.80 FL	*- FL
41	1	L85354-48030 J0	*COVER HEADLAMP	Not Necessary	32.20 FL	*- FL
42	1	L85361-48010	*BRACKET WASHER	Necessary	47.10 FL	*47.10 FL
43	1	L85362-48010	*BRACKET WASHER	Necessary	47.10 FL	*47.10 FL
44	1	L85208-48110	*ACTUATOR SUB-ASSY	Not Necessary	953.20 FL	*- FL
45	2	T90075-17011	*JOINT	Not Necessary	54.40 FL	*- FL
46	1	T90075-15088	*HOSE	Not Necessary	31.50 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1	L42611-48851	*WHEEL DISC	Scratched	4,776.80 FL	*4,776.80 FL
48	1	L67002-48160	*PANEL SUB-ASSY FR	Repair	3,614.30 FL	*- FL
Supplementary #1						
49	10	T90467-05170	*CLIP	Necessary	36.00 FL	*36.00 FL
					Sub Total (\$)	45,509.80
					- List Item Discount on L Items 30.00/30.00% (\$)	29,660.00
						8,898.00
					Total Parts (\$)	31,856.86
						20,762.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SUNDRIES	New	100.00	62.50
2	TO CHECK WIRING AND CONDUCT WATER L	New	192.00	240.00
3	TO DRILLS HOLES AND INSTALL FRONT B	New	192.00	240.00
4	TO RESET ECU & REPROGRAMME	New	240.00	240.00
5	TO CONDUCT ADJUSTMENT ON FRONT WAVE	New	192.00	240.00
6	TO CONDUCT ADJUSTMENT ON WHEEL ALIG	New	192.00	240.00
7	TO CONDUCT ADJUSTMENT ON WHEEL BALA	New	192.00	240.00
8	TO REPLACE AND REPAIR ON FRONT ENGI	New	1,152.00	0.00
9	SUPPLY SEALANT (NETT)	New	200.00	125.00
10	TO REPLACE AND REPAIR ON ACCIDENT A	New	3,840.00	3,360.00
11	TO SPRAY PAINTING ON ACCIDENT AFFEC	New	3,916.80	3,264.00
Gross Labour Cost (\$\$)			10,408.80	8,251.50
- 0.00/20.00% Labour Discount (\$\$)			0.00	1,650.30
Gross Labour after Discount (\$\$)			10,408.80	6,601.20

Report was unsubmitted during this print-out.

< END OF ESTIMATES >