Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: ECICS Limited From: LKK Auto Consultants Pte Ltd

10 Eunos Road 851 Ubi Ave 1 #01-25#09-04A Singapore Post CentrePaya Ubi Industrial ParkSingapore 408600Singapore 408933

Attn: Muhammad Afiq Bin Mohamed Kamal Date: 25 Jun 2024

Preliminary Advice

Vehicle No : SNP5916A Accident Date : 21/06/2024

Make : LEXUS RX300 Policy No. : MPC24A0C121800

Assignment Date : 24/06/2024 Excess : \$\$500.00

Addtional Excess : S\$500.00

Date of Inspection : 24/06/2024 Est. Duration of Repair : 7

Inspection At : BORNEO MOTORS (S) PTE LTD (PANDAN)

2 PANDAN CRESCENT SINGAPORE 128462

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	42,240.46
Revised Amount	:S\$	26,183.51
Check Items (Estimated)	:S\$	4,974.34
Total	:S\$	31,157.85

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	132,000.00
COE / PARF Rebate	:S\$	62,657.00
Salvage Value	:S\$	

Margin for Repair :S\$ 69,343.00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly
	let us have your authorisation.

) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.