

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SDZ 6677Z

	REPLACEMENT OF PARTS					
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)		
1	N/S REAR DOOR	TO REPAIR SEE LABOUR	\$3,826.00	\$0.00		
1	N/S REAR DOOR CHROME MOULDING	NOT NECESSARY	\$390.00	\$0.00		
1	REAR WINDSCREEN WITH MOULDING	NOT NECESSARY	\$1,626.00	\$0.00		
1	N/S REAR FENDER	TO REPAIR SEE LABOUR	\$5,258.00	\$0.00		
1	N/S REAR FENDER INNER SHIELD	NOT NECESSARY	\$320.00	\$0.00		
1	REAR BUMPER	CUT/TORN	\$2,233.00	\$1,865.15		
1	N/S REAR BUMPER SIDE RETAINER	NOT NECESSARY	\$254.00	\$0.00		
1	REAR BUMPER CHROME MOULDING	NECESSARY	\$156.00	\$132.70		
1	N/S REAR RIM	CUT	\$3,594.00	\$1,500.00		
1	N/S REAR UPPER ARM	NOT NECESSARY	\$844.00	\$0.00		
1	N/S REAR UPPER CONTROL ARM	NOT NECESSARY	\$577.00	\$0.00		
1	N/S REAR UPPER THRUST ARM	NOT NECESSARY	\$565.00	\$0.00		
1	N/S REAR LOWER ARM	TWISTED	\$1,210.00	\$811.00		
1	N/S REAR KNUCKLE ARM	BENT	\$1,929.00	\$1,494.80		
1	N/S REAR WHEEL BEARING	DAMAGED	\$769.00	\$622.30		
1	N/S REAR AIR MATIC	NOT NECESSARY	\$4,286.00	\$0.00		
	LESS 5.00% DISCOUNT		(\$1,391.85)	(\$321.30)		
			\$26,445.15	\$6,104.65		

Special Nett							
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)			
1	SET N/S REAR DOOR INNER TRIM CLIPS (SN)	NOT NECESSARY	\$40.00	\$0.00			
1	REAR WINDSCREEN INNER SEAL (SN)	NOT NECESSARY	\$80.00	\$0.00			
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	\$40.00	\$0.00			
1	SET N/S REAR FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	\$40.00	\$0.00			
1	SET REAR BUMPER CLIP (SN)	NECESSARY	\$40.00	\$40.00			
1	SET REAR BUMPER RIVET (SN)	NOT NECESSARY	\$60.00	\$0.00			
		\$300.00	\$40.00				



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Labour					
Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$		
TO TRANSFER DOOR GLASS	NOT NECESSARY	\$120.00	\$0.00		
TO TRANSFER DOOR MECHANISM	NOT NECESSARY	\$120.00	\$0.00		
TO RESET DOOR CENTRAL LOCKING USING DIAGNOSTIC SCANNER	NOT NECESSARY	\$350.00	\$0.00		
TO RESET POWER WINDOW	NOT NECESSARY	\$350.00	\$0.00		
TO REMOVE / REFIT REAR WINDSCREEN GLASS	NOT NECESSARY	\$150.00	\$0.00		
TO REMOVE / REFIT INNER TRIMS AND GARNISHES	NOT NECESSARY	\$350.00	\$0.00		
TO TRANSFER AND BALANCE TYRES	NOT NECESSARY	\$50.00	\$0.00		
TO REPLACE UNDERCARRIAGE		\$400.00	\$120.00		
TO CONDUCT 4 WHEEL ALIGNMENT		\$120.00	\$80.00		
TO CALIBRATE AIR MATIC	NOT NECESSARY	\$350.00	\$0.00		
TO RUSTPROOF ACCIDENT DAMAGE AREA	NOT NECESSARY	\$150.00	\$0.00		
TO REPAIR INNER PANEL, ACCIDENT DAMAGE AREA, CUT / REWELD N/S REAR FENDER, REPLACEMENT OF PARTS AND ALIGN THE SAME. INCLUSIVE OF THE REPAIR OF N/S REAR DOOR AND N/S REAR FENDER		\$1,200.00	\$500.00		
TO PUTTY AND SPRAY PAINT ON ACCIDENT DAMAGE AREA		\$1,200.00	\$600.00		
		\$4,910.00	\$1,300.00		
GRAND TOTAL		\$31,655.15	\$7,444.65		
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$5,900.00		
Report Ref No: CS/LIP24100237/Uqh3e2					

MARKET VALUE: \$123,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$91,710.00=NETT VALUE: \$31,290.00

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.