

5b.

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	LIBERTY INSURAN	ICE PTE LTD	Ref:	CS/LIP24100237/Uqh3e2	
	ONE RAFFLES QUAY #25-01 NORTH TOWER		Date:	28/10/2024	
	SINGAPORE 048583		Code:	LIP	
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	YN 9669S	Veh. Inspected	SDZ 6677Z	
	Policy No.	-	Coverage	0	
	Claim No.	AVS24/3163	Excess	\$0.00	
	Assign From	ANDY SEAH	Assign Date	14/10/2024	
2. Vehicle Details					
	Make & Model	B.M.W. 730LI (A)	C.C	1998	
	Engine No.	11379996B48B20B	Year of Reg.	28/12/2017	
	Chassis No.	WBA7E02080G245369	Colour	WHITE	
	Odometer	123769 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	255/35ZR20	CONTINENTAL	6	
	L/H Front Tyre	255/35ZR20	CONTINENTAL	6	
	R/H Rear Tyre	285/30ZR20	CONTINENTAL	6	
	L/H Rear Tyre	285/30ZR20	CONTINENTAL	6	
4.	1. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.					
5. General Information					
	Accident Date	10/10/2024	Inspection Date	15/10/2024	
	Survey held at	FALCON-AIR AUTO SERVICES PTE LTD BLK 9006 TAMPINES ST 93 #01-200 SINGAPORE 528840			
5a. Remarks					

Estimate Days of Repair

A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days

B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.